



Missing HI-Z Lead

**Damaged HI-Z Shield
Pigtail Lead Wires**

**Broken terminal block -
missing Lo-Z terminal and
wire, and strain relief
clamp**

Systems 9 - Exhibit No. 9B - Photo 18. Figure 18g. Representative damage to a fuel probe, wiring and terminal block from N93119.