



Systems 9 - Exhibit No. 9B - Photo 19. Figure 19g. Representative damage to a fuel probe wiring from