



Systems 9 - Exhibit No. 9B - Photo 2. Figure 2c. As received condition of the SPR circuit breaker. The upper arrow highlights the corroded terminal hardware. The lower arrow highlights the cracked housing.