

Systems 9 - Exhibit No. 9B - Photo 20. Figure 20g. Representative damage to a fuel probe wiring fromo N93119.