



Systems 9 - Exhibit No. 9B - Photo 21. Figure 21g. Representative damage to a fuel probe wiring from