



Systems 9 - Exhibit No. 9B - Photo 22. Figure 22a. Internal view of the plunger and guide, red lubricant, (at white arrow, chemically analyzed) and rocker arm of switch S11. Mold runner mark is apparent at the black