



Systems 9 - Exhibit No. 9B - Photo 23. Figure 23a. Normally open contact surface from the left jettison switch exhibiting typical wear.