



Systems 9 - Exhibit No. 9B - Photo 23. Figure 23g. Compression damage from strain relief clamp (N93110 compensator sample #45).