

Example of heavily
corroded flat fracture
surface



Systems 9 - Exhibit No. 9B - Photo 30. Figure 30g. SEM image--broken shielding wire strand fracture surface.