



Systems 9 - Exhibit No. 9B - Photo 33. Figure 33g. Damage to PTFE insulation caused by serrated surface and clamping pressure.