



Systems 9 - Exhibit No. 9B - Photo 41. Figure 41g-2. Elemental X-ray microanalysis of film residue. Note high concentrations of copper, silver, and sulfur at points 1 and 2. These were taken on the film material. Point 3 was taken on the PTFE insulation.