

Conductor strands visible where PTFE insulation was compressed within "P" strain relief clamp shown in Figure 45



Systems 9 - Exhibit No. 9B - Photo 46. Figure 46g. Compression damaged Hi-Z pigtail lead wire from compensator (model no. FG6C2, serial no. Y-147) from