



Systems 9 - Exhibit No. 9B - Photo 5. Figure 5a. Left jettison switch screw terminals exhibiting corrosion from salt water exposure. Note the exposed copper from the solder lug (arrow).