



Systems 9 - Exhibit No. 9B - Photo 5. Figure 5c. The moving line contact of the SPR circuit breaker has a tarnished appearance. Black arrow highlights mechanical wear from the making and breaking of the contacts. White arrow indicates the fibrous residue