



Systems 9 - Exhibit No. 9B - Photo 6. Figure 6c. The moving load contact of the SPR circuit breaker has a tarnished appearance. The arrow highlights the mechanical wear from making and breaking of the