



Systems 9 - Exhibit No. 9B - Photo 8. Figure 8f. Lateral cross section of a different wire than from figure 7. Again note depth variability of the mark from right to left. Note all three insulation layers were again penetrated.