



Systems 9 - Exhibit No. 9B - Photo 9. Figure 9c. The stationary line contact of the SPR circuit breaker has a tarnished appearance. Arrow highlights the mechanical wear from the making and breaking of the contacts.