

**Analysis of A Submitted Wire  
(Failure Analysis)**

21 October 1997

**Evaluation Report  
(4349INRD/NTSB)**

Report No. WL/MLS 97-091

**AUTHOR**

George A. Slenski  
Materials Integrity Branch (WL/MLSA)  
2179 Twelfth Street Suite 1  
Wright-Patterson Air Force Base, Ohio 45433-7718

**REQUESTER**

Mr. Robert Swaim  
National Transportation Safety Board  
490 L'Enfant Plaza, East, S.W.  
Washington DC 20594

**DISTRIBUTION STATEMENT F:** Further dissemination only as directed by (National Transportation Safety Board) (21 October 1997) or DoD higher authority.

000072

### **ACKNOWLEDGMENTS**

As is usual for this type of investigation the efforts of others are critical to its success. The author would like to thank Mr. John Ziegenhagen of the University of Dayton Research Institute for expert photography.

**TABLE OF CONTENTS**

	Page
LIST OF FIGURES . . . . .	iv
PURPOSE . . . . .	1
FACTUAL DATA . . . . .	1
SUMMARY OF FINDINGS . . . . .	4

**LIST OF FIGURES**

Figure		Page
1	Wire sample submitted for analysis. The insulation exhibited blackened areas (black arrows) and mechanical damage (white arrows).	1
2	Multiple images of the largest blackened and thermally damaged area on the submitted wire.	2
3	Blackened and thermally damaged area on wiring. Note raised area (arrow).	3
4	Typical mechanically damaged insulation area. Note the damage reveals the multiple layered insulation construction.	4