



Systems 9 - Exhibit No. 9E - Photo No. 2 - Evidence of arcing along emergency light wire routing (to right of upper deck - N93119). ATA 24-50-00.