

of motor windings from jettison/override fuel pumpos fromN93119. Center winding was heated until thermal fuses opened and is visibly darker. ATA 28-31-01