

DOCKET NO.: SA-517
EXHIBIT NO. 9B

NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.

SYSTEMS GROUP CHAIRMAN’S FACTUAL REPORT
ATTACHMENT 1
ACCIDENT SITE PHOTOGRAPHS

By: Gregory Phillips
(10 pages)

Attachment 1
Accident Site Photographs

- Photo 1: Side view of empennage
- Photo 2: Side view of *Aft* Fuselage near empennage
- Photo 3: Side view of Forward Fuselage Area
- Photo **4**: Cockpit Area
- Photo **5**: Cockpit Area
- Photo 6: Cockpit Area
- Photo 7: First Officer's Instrument Panel (as viewed at scene)
- Photo **8**: Pilot's Center Instrument Panel
- Photo 9: First Officer's Instrument Panel (as viewed at scene)
- Photo 10: Close-up of First Officer's Instrument Panel (as viewed at scene)
- Photo 11: Close-up of First Officer's Instrument Panel (as viewed at scene)
- Photo 12: F/O Instr Panel, Portion of Auto Flt Control Panel, Center Instr Panel
- Photo 13: Captain's Instrument Panel
- Photo **14**: Right Side VHF Control Panel
- Photo 15: Close-up of Captain's Instrument Panel
- Photo 16: Automatic Flight Control Panel
- Photo 17: Throttle Quadrant
- Photo **18**: Flight Engineer's Fuel Control Panel
- Photo 19: Flight Engineer's Engine Instrument Panel
- Photo 20: Lower Center Pedestal Area