



Systems 9 - Exhibit No. 9B - Photo 3. View (looking forward) of left inboard ground spoiler panel. Note the fracture (arrow) just inboard of actuator hinge (1) and extensive soot damage.