



Systems 9 - Exhibit No. 9B - Photo 5. View (looking forward) of right inboard ground spoiler panel. Note the fracture (arrow) just outboard of actuator hinge (2).