



Systems 9 - Fuel Quantity Indication System - Photo 37. Forward spar, breach in left side of fuselage at about station 920 (along route of missing W480 wires), and generator cables for engines 1,2 and APU generator.