

Systems 9 - Fuel Quantity Indicators - Photo 17. Damaged Indicator examined October 28, 1998, at Boeing EQA Lab.