



Systems 9 - Photo 10. View looking inboard of spoiler 8. Note damage to inboard trailing edge. There was no damage to the leading edge of the flap panel.