



Systems 9 - Photo 12. Airplane 7. B-747 Drill shavings on wire bundles immediately beneath floor structure repair shown in photo 11. Fluid stain visible on structure.