



Systems 9 - Photo 17. Airplane 9. B-747 Raceway clamp at STAT 400 opening has no retainer. Pressing upward on wires revealed that the quantity of wires prevented installation of a retainer. Mixed wire types and fresh white wire insulation is visible.