



Systems 9 - Photo 32. Airplane 14. B-747 cockpit floor aft and outboard of First Officer seat. Wire bundle was stiff and not flexible, containing bared wire fragments, metal shavings, dirt, and a mixture of wire types. New wires laid on existing bundle.