



Systems 9 - Photo 41. Airplane 19. B767 burned wires seen after chiller removed from the rack over the oxygen tank. The edge of the chiller was near the burned area, damaged wire insulation was found on unburned wires, and foam on chiller burned.