



Systems 9 - Photo 51. (Feb. 21-25, 1998) B-747 opening and wire behind bundle at left of photo 50. Clamp sprung open when plastic panduit (ty-wrap) was removed. Visible are degraded foam, brown on wires, and power cables routed with system wires.