

1991 (Rec. A-91-70). Bay behind burned area contains two inches of lint fallen over generator cables, plastic wrapper, nutplate, hydraulic "B-nut," foil between generator cables, hose clamp, and paper.