

compartment beneath cockpit. Drill shavings shown on wires and shaving are between cable and wires. Loose string, wire chafe, and lint are visible. (Left edge of photo