



Systems 9 - Photo 9. View looking forward of spoiler 1. Note damage to inboard trailing edge. There was no damage to the leading edge of the flap panel.