

NTSB Investigation of Merrimack Valley, MA, Fires & Explosions
NTSB Investigation PLD18MR003

Page 1 of 1

Name	McGinnity, Steve
Company & Department	Columbia Gas, Meter & Regulation Department
Title	M&R Technician
Date of Interview	September 21, 2018

I have reviewed the transcript of my NTSB interview from the referenced investigation. I have answered questions to the best of my ability, but without the opportunity to review documents to refresh my recollection. Some of what I remember may be based on what others told me. My requested corrections and clarifications are as noted below.

Page	Line	Current	Request	Reason
6	21	L&G	LNG	Transcription Error
8	5	which I knew right away was wrong	so I knew right away something was wrong	Clarification
10	18 & 24	tie-in hull	tie-in hole	Transcription Error
11	2	tie-in hull	tie-in hole	Transcription Error
14	24	The worker's usually set...	At this time of year, the worker's usually set...	Clarification
16	16	It does say that.	It does say that, but the worker regulator is not allowed to be set above the MAOP.	Clarification
20	7	all the piping.	all the vault piping.	Clarification
20	17, 19 & 21	Mass aft	Mass Ave	Transcription Error
25	22	They	The Engineering Department	Clarification
33	9	Probably four or five.	If work is being done near a regulator vault it is fairly routine to stand by at the vault with a pressure gauge and cell phone. If work is being done further away, it has been four or five years.	Clarification
34	22	Mike	Larry	Transcription Error