



## Track Inspection & FRA Reports

[FRA Inspectors Movement and Defect Report](#)  
 [About](#)  
 [Help](#)

Return To: [UP Employees Home](#)

Fri, March 10, 2017 09:42:03 AM

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/10/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/10/2015 03:17:15 PM

**Date Inspection Closed by Inspector:** 03/10/2015 03:09:46 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

#### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Comments

--

#### Track Defects

No track defect records found

#### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

#### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	03/10/2015	Tightened adjustable rail braces	03/10/2015		
ESTHERVILLE SUB	8253 SIMN	32.43 0.00	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	03/10/2015	Installed bolt or bolts	03/10/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 03/11/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/11/2015 04:51:11 PM

**Date Inspection Closed by Inspector:** 03/11/2015 04:48:44 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

Also Accompanied by DH Deurloo, MTM, Defects Are Noted , on FRA Report # 28. Filed By Brown

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/14/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 03/14/2015 04:51:57 PM

**Date Inspection Closed by Inspector:** 03/14/2015 04:41:12 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	41.51	Defect Length : 0	113BA-113.B10 - Ordinary break	Repaired Before Traffic	03/14/2015	Bars applied	03/14/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
	8253 SIMN	31.03		121E-121.E - Less than 2	Repaired		Installed bolt or			

ESTHERVILLE SUB	-	31.01	Number of Bolts : 2	bolts	Before Traffic	03/14/2015	bolts	03/14/2015		
-----------------	---	-------	---------------------	-------	----------------	------------	-------	------------	--	--

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/17/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 03/17/2015 04:07:10 PM

Date Inspection Closed by Inspector: 03/17/2015 04:00:08 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	39.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	39.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	9.19 9.16		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	03/17/2015	Removed obstruction	03/17/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/18/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 03/18/2015 04:31:24 PM

Date Inspection Closed by Inspector: 03/18/2015 04:28:20 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77/269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02/117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02/729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02/767	78.41	78.43	No	?	?	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	65.50		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/18/2015	Corr from Trk Mtce Plan	03/31/2015		
ESTHERVILLE SUB	8254 SIMN -	65.50		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/18/2015	Corr from Trk Mtce Plan	03/31/2015		
ESTHERVILLE SUB	8254 SIMN -	67.40		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/18/2015	Corr from Trk Mtce Plan	03/31/2015		
ESTHERVILLE SUB	8268 SIMN -	71.65		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/18/2015	Corr from Trk Mtce Plan	03/25/2015		
ESTHERVILLE SUB	8268 SIMN -	71.65		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/18/2015	Corr from Trk Mtce Plan	03/25/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 -005		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 03/21/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/21/2015 03:01:11 PM

Date Inspection Closed by Inspector: 03/21/2015 03:00:26 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 03/24/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 03/24/2015 06:38:22 PM

Date Inspection Closed by Inspector: 03/24/2015 06:36:21 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	39.85	Percent Defect : <b>100</b>	113BE-113.B14 - Broken or defec	Repaired Before Traffic	03/24/2015	Replaced Rail	03/24/2015		

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.61 0.00	Number of Bolts : <b>3</b>	121E-121.E - Less than 2 bolts	Repaired Before Traffic	03/24/2015	Installed bolt or bolts	03/24/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/28/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 03/28/2015 03:03:10 PM

**Date Inspection Closed by Inspector:** 03/28/2015 02:59:49 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--

### Track Defects

No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	48.49 48.49		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	03/28/2015	Tightened frog bolt	03/28/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 03/31/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/31/2015 04:41:55 PM

**Date Inspection Closed by Inspector:** 03/31/2015 04:31:33 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURL00	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURL00	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURL00	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURL00	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURL00	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURL00	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURL00	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURL00	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURL00	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURL00	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	51.70		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/31/2015	Corr from Trk Mtce Plan	04/20/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 04/04/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/04/2015 04:50:58 PM



Date Inspection Closed by Inspector: 04/04/2015 04:47:38 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.40		121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/04/2015	Installed bolt or bolts	04/04/2015		

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	8.40 8.37		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	04/04/2015	Tightened frog bolt	04/04/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 04/07/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

Date Inspection Uploaded into the Central System: 04/07/2015 03:59:21 PM

Date Inspection Closed by Inspector: 04/07/2015 03:53:33 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	39.30		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/07/2015	Corr from Trk Mtce Plan	04/30/2015		
ESTHERVILLE SUB	8253 SIMN	39.30		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/07/2015	Corr from Trk Mtce Plan	04/30/2015		
ESTHERVILLE SUB	8253 SIMN	42.40		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/07/2015	Corr from Trk Mtce Plan	04/30/2015		
ESTHERVILLE SUB	8253 SIMN	43.75		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/07/2015	Corr from Trk Mtce Plan	04/30/2015		
ESTHERVILLE SUB	8253 SIMN -	31.03		121E-121.E - Less than 2 bolts	Repaired Before Traffic	04/07/2015	Installed bolt or bolts	04/07/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 04/11/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 04/11/2015 04:05:42 PM

**Date Inspection Closed by Inspector:** 04/11/2015 03:58:20 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
		8254	-						

TWIN CITIES	ESTHERVILLE SUB	SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	60.95		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/11/2015	Corr from Trk Mtce Plan	04/24/2015		
ESTHERVILLE SUB	8254 SIMN -	61.63		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/11/2015	Corr from Trk Mtce Plan	04/24/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 005	70.78	8268 INDU	02 -761		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 503	71.38	8268 YARD	02 -502		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/13/2015	<b>Inspected By:</b> Joshua Gollob
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Joshua Gollob
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 04/13/2015 03:16:18 PM

**Date Inspection Closed by Inspector:** 04/13/2015 03:16:19 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	34.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	34.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

Inspected TRK from MP 0-34 Estherville Sub

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	11.25		103D-103.D - Fouled or insuffi	Scheduled for Repair	04/13/2015	Corr from Trk Mtce Plan	05/12/2015		Needs rip rap and ballast. Boom truck

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 04/14/2015      **Inspected By:** Joshua Gollob  
**Inspection Type:** FRA Required      **Relief Inspector:** Joshua Gollob  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/15/2015 07:02:56 AM

**Date Inspection Closed by Inspector:** 04/15/2015 07:02:56 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		34.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	50.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		34.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	50.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Comments**

inspect TRK from MP34-50 Estherville Sub

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 04/15/2015      **Inspected By:** Joshua Gollob  
**Inspection Type:** FRA Required      **Relief Inspector:** Joshua Gollob  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/15/2015 03:14:38 PM

**Date Inspection Closed by Inspector:** 04/15/2015 03:14:39 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Inspected TRK from 78.4-50 Estherville and Mallard-Rolf Tara									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/16/2015	<b>Inspected By:</b> Joshua Gollob
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Joshua Gollob
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 04/17/2015 07:04:22 AM

Date Inspection Closed by Inspector: 04/17/2015 07:04:22 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									
Inspected TRK From MP28-58.25 Tara Sub and 32.2-0Estherville Sub									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/22/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 04/22/2015 05:50:26 PM  
 Date Inspection Closed by Inspector: 04/22/2015 05:47:16 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02/103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02/103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Comments									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
 FRA Track Inspection & Defect Report**

Inspection Date: 04/23/2015 Inspected By: Gary Brockman  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 04/24/2015 07:37:42 AM  
 Date Inspection Closed by Inspector: 04/23/2015 05:16:07 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									
Estherville Sub Inspected under UP Babcock, Trk Warrants # 6415 and # 3983, Between Mp 33 And MP 78.4									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	63.20		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/23/2015	Corr from Trk Mtce Plan	05/01/2015		
	8254									

ESTHERVILLE SUB	SIMN -	63.30	109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/23/2015	Corr from Trk Mtce Plan	05/01/2015		
-----------------	-----------	-------	------------------------------------	-------------------------	------------	----------------------------	------------	--	--

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/25/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 04/25/2015 04:50:39 PM

**Date Inspection Closed by Inspector:** 04/25/2015 02:50:58 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	34.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	34.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
		8253			8253			

Walked	ESTHERVILLE SUB	SIMN	-	31.03	SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	04/25/2015	Tightened adjustable rail braces	04/25/2015		
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	04/25/2015	Tightened adjustable rail braces	04/25/2015		
ESTHERVILLE SUB	8253 SIMN -	32.19 32.18		133A3-133.A3 - Loose, worn, or	Repaired Before Traffic	04/25/2015	Tightened connecting rod fastener	04/25/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/30/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 04/30/2015 05:37:02 PM

**Date Inspection Closed by Inspector:** 04/30/2015 05:33:57 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE



Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	61.90		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/30/2015	Corr from Trk Mtce Plan	05/08/2015		
ESTHERVILLE SUB	8254 SIMN -	61.90		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/30/2015	Corr from Trk Mtce Plan	05/08/2015		
ESTHERVILLE SUB	8254 SIMN -	70.43		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/30/2015	Corr from Trk Mtce Plan	05/05/2015		
ESTHERVILLE SUB	8254 SIMN -	70.43	Defect Length : 120	113B7-113.B7 - Broken base	FRA Remedial Actions E and I	04/30/2015	Corr from Trk Mtce Plan	05/05/2015		
ESTHERVILLE SUB	8254 SIMN -	70.43	Defect Length : 120	113B7-113.B7 - Broken base	FRA Remedial Actions E and I	04/30/2015	Corr from Trk Mtce Plan	05/05/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 05/02/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 05/02/2015 03:51:03 PM**Date Inspection Closed by Inspector:** 05/02/2015 03:43:14 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments****Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	9.19 9.16		133AI-133.A18 - Obstruction in	Repaired Before Traffic	05/02/2015	Removed obstruction	05/02/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 05/05/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/05/2015 02:55:26 PM**Date Inspection Closed by Inspector:** 05/05/2015 02:50:35 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	47.35	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/05/2015	Installed bolt or bolts	05/05/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 05/09/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/09/2015 04:19:50 PM

**Date Inspection Closed by Inspector:** 05/09/2015 04:14:12 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
Track Traversed Information									

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	50.75		109B2-109.B2 - Crossties not ef	Scheduled for Repair	05/09/2015	Corr from Trk Mtce Plan	05/20/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	9.19 9.16		135D-135.D - Heel of switch in	Scheduled for Repair	05/09/2015	Corr from Trk Mtce Plan	05/28/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

Inspection Date: 05/12/2015 Inspected By: Gary Brockman  
Inspection Type: FRA Required Relief Inspector: Data not entered  
Weather: Clear How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 05/12/2015 03:38:53 PM  
Date Inspection Closed by Inspector: 05/12/2015 03:29:24 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/	Zone/	Begin	End	Rail Xing	Director	Manager	Track Description
--------------	-------------	------	-------	-------	-----	-----------	----------	---------	-------------------

		Trk Type	Track	MP	MP	Insp			
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	47.27		103A-103.A - Fouled or insuffi	Scheduled for Repair	05/12/2015	Corr from Trk Mtce Plan	06/10/2015		
ESTHERVILLE SUB	8253 SIMN	47.27		109B2-109.B2 - Crossties not ef	Scheduled for Repair	05/12/2015	Corr from Trk Mtce Plan	06/10/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 05/16/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/16/2015 04:45:20 PM

**Date Inspection Closed by Inspector:** 05/16/2015 04:36:21 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.52		109B2-109.B2 - Crossties not ef	Scheduled for Repair	05/16/2015	Corr from Trk Mtce Plan	05/22/2015		
ESTHERVILLE SUB	8254 SIMN -	69.52		109B2-109.B2 - Crossties not ef	Scheduled for Repair	05/16/2015	Corr from Trk Mtce Plan	05/22/2015		
ESTHERVILLE SUB	8254 SIMN -	69.52		109B2-109.B2 - Crossties not ef	Scheduled for Repair	05/16/2015	Corr from Trk Mtce Plan	05/22/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	70.56 70.55		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	05/16/2015	Removed obstruction	05/16/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 05/19/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/19/2015 03:50:31 PM

**Date Inspection Closed by Inspector:** 05/19/2015 03:46:22 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Comments****Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIDE 02 103	31.07	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/19/2015	Installed bolt or bolts	05/19/2015		

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	47.18 47.18	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	05/19/2015	Installed bolt or bolts	05/19/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**

## FRA Track Inspection & Defect Report

Inspection Date: 05/21/2015	Inspected By: Gary Brockman
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 05/21/2015 03:52:05 PM

Date Inspection Closed by Inspector: 05/21/2015 03:51:24 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.41	78.43	No	?	?	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	58.70		109B2-109.B2 - Crossties not ef	Scheduled for Repair	05/21/2015	Corr from Trk Mtce Plan	06/19/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found



## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 05/23/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/23/2015 01:50:49 PM

**Date Inspection Closed by Inspector:** 05/23/2015 01:45:36 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	31.03 31.01		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	05/23/2015	Tightened frog bolt	05/23/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 05/26/2015    **Inspected By:** LEE Cameron  
**Inspection Type:** FRA Required    **Relief Inspector:** Lee Cameron  
**Weather:** Data not entered    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 05/26/2015 01:29:38 PM

**Date Inspection Closed by Inspector:** 05/26/2015 01:29:38 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

		SIMN							
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									
34.5-0 for gary brockman									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 05/28/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 05/28/2015 09:46:06 PM

Date Inspection Closed by Inspector: 05/28/2015 09:39:00 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	49.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	49.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Comments**

Track Traversed on EC-5 , Defects Noted

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.95 48.95	Deviation Profile : 2.75	63A2-63.A2 - Deviation from un	Repaired Before Traffic	05/28/2015	Tamped to Surface Track	05/28/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 05/29/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/30/2015 12:04:18 AM

**Date Inspection Closed by Inspector:** 05/29/2015 11:57:18 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	71.65	Gage Measurement : 57.75	53B3-53.B3 - Gage dimension on	Repaired Before Traffic	05/29/2015	Gaged track	05/29/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 -005		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 06/02/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/02/2015 03:45:17 PM

**Date Inspection Closed by Inspector:** 06/02/2015 03:44:12 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	1.77		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/02/2015	Corr from Trk Mtce Plan	06/18/2015		
ESTHERVILLE SUB	8253 SIMN	34.87		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/02/2015	Corr from Trk Mtce Plan	06/30/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 06/06/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/06/2015 07:55:46 PM

**Date Inspection Closed by Inspector:** 06/06/2015 07:49:38 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	49.00		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/06/2015	Corr from Trk Mtce Plan	06/30/2015		
ESTHERVILLE SUB	8268 SIMN -	77.77		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/06/2015	Corr from Trk Mtce Plan	06/26/2015		
ESTHERVILLE SUB	8254 SIMN -	58.30		127A-127.A - Failure of fasten	Scheduled for Repair	06/06/2015	Corr from Trk Mtce Plan	06/19/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 06/10/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/10/2015 04:04:22 PM

**Date Inspection Closed by Inspector:** 06/10/2015 03:58:03 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
Also Accompanied By DH Deurloo, MTM, Defect s are noted on FRA Report Filed by Secora, Todays date									

### Track Defects

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/12/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/12/2015 04:07:04 PM

**Date Inspection Closed by Inspector:** 06/12/2015 03:57:30 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	62.60		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/12/2015	Corr from Trk Mtce Plan	07/01/2015		
ESTHERVILLE SUB	8254 SIMN -	68.50		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/12/2015	Corr from Trk Mtce Plan	07/01/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 06/16/2015	Inspected By: Gary Brockman
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 06/16/2015 03:06:33 PM

Date Inspection Closed by Inspector: 06/16/2015 03:03:30 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	28.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.41	78.43	No	?	?	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	28.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	65.80		37C1-37.C1 - Vegetation interf	Repaired Before Traffic	06/16/2015	Removed vegetation around track	06/16/2015		
ESTHERVILLE SUB	8268 YARD 02 002	71.00		37C3-37.C3 - Excessive vegetat	Repaired Before Traffic	06/16/2015	Removed vegetation from walk way and toepath	06/16/2015		
ESTHERVILLE SUB	8268 YARD 02 002	71.00		37C3-37.C3 - Excessive vegetat	Repaired Before Traffic	06/16/2015	Removed vegetation from walk way and toepath	06/16/2015		
ESTHERVILLE SUB	8268 YARD 02 002	71.00		37C3-37.C3 - Excessive vegetat	Repaired Before Traffic	06/16/2015	Removed vegetation from walk way and toepath	06/16/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 -005		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 06/17/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 06/17/2015 03:15:00 PM

**Date Inspection Closed by Inspector:** 06/17/2015 03:11:03 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	30.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	30.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	8.40 8.37		133A9-133.A9 - Loose or missing	Repaired Before Traffic	06/17/2015	Tightened adjustable rail braces	06/17/2015		
ESTHERVILLE SUB	8253 SIMN -	8.40 8.37		133A9-133.A9 - Loose or missing	Repaired Before Traffic	06/17/2015	Tightened adjustable rail braces	06/17/2015		
ESTHERVILLE SUB	8253 SIMN -	9.19 9.16		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	06/17/2015	Tightened frog bolt	06/17/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	30.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found



## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 06/20/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/20/2015 04:52:30 PM

**Date Inspection Closed by Inspector:** 06/20/2015 04:50:51 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

Special Inspection, FLASH FLOODING MP 6.0 to MP 78.0

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point

## Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.95 48.95		135D-135.D - Heel of switch in	Scheduled for Repair	06/20/2015	Corr from Trk Mtce Plan	06/30/2015		
ESTHERVILLE SUB	8254 SIMN -	48.59 48.59		133A7-133.A7 - Worn or missing	Repaired Before Traffic	06/20/2015	Replaced cotter pins	06/20/2015		
ESTHERVILLE SUB	8253 SIMN	48.49 48.49		133A7-133.A7 - Worn or missing	Repaired Before Traffic	06/20/2015	Replaced cotter pins	06/20/2015		

## Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		46.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

Union Pacific Railroad  
FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 06/23/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 06/23/2015 03:15:17 PM

Date Inspection Closed by Inspector: 06/23/2015 03:07:29 PM

## Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.75	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.75	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

## Comments

--

## Track Defects

No track defect records found

## Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.43 0.00		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/23/2015	Corr from Trk Mtce Plan	06/30/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	30.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.75	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 06/26/2015      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 06/26/2015 02:38:21 PM

**Date Inspection Closed by Inspector:** 06/26/2015 02:38:21 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 06/27/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered

Weather: Clear How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 06/27/2015 05:05:05 PM

Date Inspection Closed by Inspector: 06/27/2015 04:56:31 PM

## Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

## Comments

## Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	54.06		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/27/2015	Corr from Trk Mtce Plan	07/24/2015		
ESTHERVILLE SUB	8254 SIMN -	54.17		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/27/2015	Corr from Trk Mtce Plan	07/24/2015		

## Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

## Switch Defects

No switch defect records found

## Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	30.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253		32.20	46.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

		SIMN						
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 06/30/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 06/30/2015 03:41:22 PM

**Date Inspection Closed by Inspector:** 06/30/2015 03:40:20 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

Estherville Sub, MP 48.49 to MP 35.0 ,Inspected By DRDickey , Rolfe Section Foreman.

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.05		121C2-121.C2 - Center cracked o	Repaired Before Traffic	06/30/2015	Replaced joint bars	06/30/2015		
ESTHERVILLE SUB	8253 SIMN	32.45	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	06/30/2015	Installed bolt or bolts	06/30/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 07/03/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/03/2015 04:59:04 PM

**Date Inspection Closed by Inspector:** 07/03/2015 04:55:06 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02-001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02-002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	68.30		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/03/2015	Corr from Trk Mtce Plan	07/29/2015		
ESTHERVILLE SUB	8254 SIMN -	68.30		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/03/2015	Corr from Trk Mtce Plan	07/31/2015		
ESTHERVILLE SUB	8254 SIMN -	68.30		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/03/2015	Corr from Trk Mtce Plan	07/29/2015		
ESTHERVILLE SUB	8254 SIMN -	68.35		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/03/2015	Corr from Trk Mtce Plan	07/29/2015		
ESTHERVILLE SUB	8254 SIMN -	68.45		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/03/2015	Corr from Trk Mtce Plan	07/29/2015		
ESTHERVILLE SUB	8254 SIMN -	68.45		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/03/2015	Corr from Trk Mtce Plan	07/29/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/07/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/07/2015 04:03:20 PM

**Date Inspection Closed by Inspector:** 07/07/2015 03:55:47 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	15.12	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	07/07/2015	Installed bolt or bolts	07/07/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/11/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 07/11/2015 04:10:02 PM

**Date Inspection Closed by Inspector:** 07/11/2015 04:00:33 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77_269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02_723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02_809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02_820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02_820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02_724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	40.40	Deviation Profile : <b>2.0625</b>	103D-103.D - Fouled or insuffi	Scheduled for Repair	07/11/2015	Corr from Trk Mtce Plan	07/31/2015		
ESTHERVILLE SUB	8253 SIMN	40.40		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/11/2015	Corr from Trk Mtce Plan	07/31/2015		
ESTHERVILLE SUB	8253 SIMN	16.28		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	07/11/2015	Removed vegetation around signs and signals	07/11/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmetsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmetsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmetsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmetsburg ICE Transfer	Railbound Manganese

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	48.49 48.49	Number of Bolts : <b>3</b>	121E-121.E - Less than 2 bolts	Repaired Before Traffic	07/11/2015	Installed bolt or bolts	07/11/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

Inspection Date: 07/14/2015    Inspected By: Gary Brockman



**Inspection Type:** FRA Required **Relief Inspector:** Data not entered  
**Weather:** Clear **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 07/14/2015 06:30:31 PM

**Date Inspection Closed by Inspector:** 07/14/2015 06:24:57 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

Estherville Sub MP 48.49 to MP 78.40, Inspected And Traversed by DHDeurloo and DC-46 Rail test Truck., Special Inspection HOT Weather Laurens Sub , MP 0.0 to MP 28.50 , 91 Degrees at 15:00

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	0.07	Deviation : 2	55A3-55.A3 - Alinement deviat	Slow Order to 10 mph	07/14/2015	Corr from Trk Mtce Plan	07/16/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 07/17/2015 **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required **Relief Inspector:** Data not entered  
**Weather:** Clear **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 07/17/2015 06:00:08 PM

**Date Inspection Closed by Inspector:** 07/17/2015 05:57:31 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

--	--	--	--	--	--	--	--	--	--

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
Special Inspection, HOT Weather. Estherville Sub MP 0.0 To Mp 48.49. 90 Degrees At 16:00 Hrs									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/18/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 07/18/2015 04:04:27 PM

Date Inspection Closed by Inspector: 07/18/2015 03:57:09 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

Special Inspection HOT Weather MP 48.49 to MP 78.43 Estherville Sub, 87 Degrees at 1500 Hrs

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	59.65	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	07/18/2015	Installed bolt or bolts	07/18/2015		
ESTHERVILLE SUB	8254 CROS	48.60		133AC-133.A12 - Loose,	Repaired	07/18/2015	Tightened frog	07/18/2015		

ZZ 269	worn, or	Before Traffic	bolt
-----------	----------	----------------	------

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	59.43 59.43		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	07/18/2015	Tightened connecting rod fastener	07/18/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 07/21/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 07/21/2015 04:08:24 PM

**Date Inspection Closed by Inspector:** 07/21/2015 03:58:59 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--

### Track Defects

Subdivision	Seg / Trk Type / Zone /	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------	----	--------------------	------------------	-----------------	----------------------	-------------------	-----------------------	---------	----------

Track									
ESTHERVILLE SUB	8253 SIDE 02 103	31.07	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	07/21/2015	Installed bolt or bolts	07/21/2015	

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/22/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 07/22/2015 03:53:26 PM

Date Inspection Closed by Inspector: 07/22/2015 03:49:40 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.41	78.43	No	?	?	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.07		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/22/2015	Corr from Trk Mtce Plan	07/31/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point

Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	77.74 77.75	Distance to nearest effective tie : <b>25</b>	109B3-109.B3 - No effective sup	213.9B	07/22/2015	Corr from Trk Mtce Plan	08/11/2015		
ESTHERVILLE SUB	8268 SIMN -	78.42 78.43		135.E1 -135.E1 - Switch stand or	Scheduled for Repair	07/22/2015	Corr from Trk Mtce Plan	08/11/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/25/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/25/2015 04:22:08 PM

**Date Inspection Closed by Inspector:** 07/25/2015 04:13:56 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

Special Inspection , Heat Tara Sub Mp 70.10 to mp 58.25,

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------------	--------------------	------------------	-----------------	----------------------	-------------------	-----------------------	---------	----------

Subdivision	Zone / Track	MP	Measurement	Nature of Defect	Action	Action Date	Repairs	Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	73.68		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/25/2015	Corr from Trk Mtce Plan	08/18/2015		
ESTHERVILLE SUB	8268 SIMN -	73.68		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/25/2015	Corr from Trk Mtce Plan	08/18/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 07/29/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 07/29/2015 03:32:44 PM

**Date Inspection Closed by Inspector:** 07/29/2015 03:27:00 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

Defects are noted on FRA Report # 76 , Filed by Secora

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/01/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 08/01/2015 02:42:07 PM

**Date Inspection Closed by Inspector:** 08/01/2015 02:32:45 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.35	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/01/2015	Installed bolt or bolts	08/01/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/04/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered

**Weather:** Clear **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 08/04/2015 03:51:13 PM

**Date Inspection Closed by Inspector:** 08/04/2015 03:41:14 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

Tara Sub MP 33.0 to MP 58.25, Inspected And Traversed BY DH Deurloo and DC-46

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	46.46	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/04/2015	Installed bolt or bolts	08/04/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/06/2015 **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required **Relief Inspector:** Data not entered  
**Weather:** Clear **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 08/06/2015 04:34:24 PM

**Date Inspection Closed by Inspector:** 08/06/2015 04:24:40 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**



### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/07/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/07/2015 02:22:59 PM

**Date Inspection Closed by Inspector:** 08/07/2015 02:19:50 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	27.84 27.82		133AF-133.A15 - Turnout or trac	Repaired Before Traffic	08/07/2015	Replaced	08/07/2015		
ESTHERVILLE SUB	8253 SIMN -	27.84 27.82		133AF-133.A15 - Turnout or trac	Repaired Before Traffic	08/07/2015	Replaced	08/07/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 08/11/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/11/2015 04:42:54 PM

**Date Inspection Closed by Inspector:** 08/11/2015 04:37:17 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	53.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	53.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	49.17	Number of Ties : 8	109BA-109.B1i - 39-foot segment	Scheduled for Repair	08/11/2015	Corr from Trk Mtce Plan	09/02/2015		
ESTHERVILLE SUB	8254 SIMN -	49.49	Number of Ties : 8	109BA-109.B1i - 39-foot segment	Scheduled for Repair	08/11/2015	Corr from Trk Mtce Plan	08/25/2015		
ESTHERVILLE SUB	8254 SIMN -	49.11		127A-127.A - Failure of fasten	Scheduled for Repair	08/11/2015	Corr from Trk Mtce Plan	08/26/2015		
ESTHERVILLE SUB	8254 SIMN -	49.11		127A-127.A - Failure of fasten	Scheduled for Repair	08/11/2015	Corr from Trk Mtce Plan	08/28/2015		
ESTHERVILLE SUB	8254 SIMN -	49.11		127A-127.A - Failure of fasten	Scheduled for Repair	08/11/2015	Corr from Trk Mtce Plan	08/28/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Seg/	Zone/	Begin	End

Service Unit	Subdivision	Trk Type	Track	MP	MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/13/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 08/13/2015 05:09:31 PM

**Date Inspection Closed by Inspector:** 08/13/2015 05:08:19 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	31.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	31.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

Special Inspection Hot Weather, Laurens Sub MP 28.5 to mp 0.0 . 85 Degrees At 1545

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	73.07		127A-127.A - Failure of fasten	Scheduled for Repair	08/13/2015	Corr from Trk Mtce Plan	08/18/2015		
ESTHERVILLE SUB	8268 SIMN -	73.10		127A-127.A - Failure of fasten	Scheduled for Repair	08/13/2015	Corr from Trk Mtce Plan	08/18/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	08/13/2015	Tightened adjustable rail braces	08/13/2015		
ESTHERVILLE SUB	8253 SIMN -	32.19 32.18		133A9-133.A9 - Loose or missing	Repaired Before Traffic	08/13/2015	Tightened adjustable rail braces	08/13/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/15/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/15/2015 02:59:26 PM

**Date Inspection Closed by Inspector:** 08/15/2015 02:56:08 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

--

**Track Defects**  
No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	8.40 8.37		135D-135.D - Heel of switch in	Repaired Before Traffic	08/15/2015	Replaced heel block bolt	08/15/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/17/2015      **Inspected By:** Dustin Dickey  
**Inspection Type:** Special      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 08/17/2015 06:21:48 PM**Date Inspection Closed by Inspector:** 08/17/2015 06:21:48 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	65.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	65.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/18/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 08/18/2015 05:10:06 PM**Date Inspection Closed by Inspector:** 08/18/2015 05:07:15 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	53.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

SIMN									
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	53.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									
Special Inspections, FLASH FLOODING. Tara Sub MP 50.0 to MP 58.25, Estherville MP 19.0 to MP 53.0 ,Inspected BY GOB. Laurens Sub MP 0.0 to MP 28.50 ,Inspected by DR Dickey Rolfe Section Foreman									

**Track Defects**  
No track defect records found

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/19/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 08/19/2015 03:40:59 PM

**Date Inspection Closed by Inspector:** 08/19/2015 03:37:59 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Special Inspection , FLASH FLOOD. Tara Sub MP 58 to MP 70									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.55	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/19/2015	Installed bolt or bolts	08/19/2015		
ESTHERVILLE SUB	8268 SIMN -	78.18	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/19/2015	Installed bolt or bolts	08/19/2015		

#### Switches Inspected

From Track	To Track

Switch Inspected by	Subdivision	Segment/Track	ZTS	Mile Value	Segment/Track	ZTS	User Switch Description	Frog Type Description
		8268 SIMN	-		8267 SIMN	-		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 -005		
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	70.57 70.56		133A9-133.A9 - Loose or missing	Repaired Before Traffic	08/19/2015	Tightened adjustable rail braces	08/19/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 08/22/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/22/2015 02:26:49 PM

**Date Inspection Closed by Inspector:** 08/22/2015 02:17:53 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253	02	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

		SIDE	103						
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	59.43 59.43		135D-135.D - Heel of switch in	Repaired Before Traffic	08/22/2015	Replaced heel block bolt	08/22/2015		
ESTHERVILLE SUB	8253 SIMN	47.18 47.18	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/22/2015	Installed bolt or bolts	08/22/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		46.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/26/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/26/2015 05:28:33 PM

**Date Inspection Closed by Inspector:** 08/26/2015 05:23:19 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
		8253	02						



TWIN CITIES	ESTHERVILLE SUB	INDU	723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.61 0.00	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/26/2015	Installed bolt or bolts	08/26/2015		
ESTHERVILLE SUB	8254 SIMN -	69.61 0.00		133A9-133.A9 - Loose or missing	Repaired Before Traffic	08/26/2015	Tightened adjustable rail braces	08/26/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	60.00	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/29/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 08/29/2015 07:39:38 PM

**Date Inspection Closed by Inspector:** 08/29/2015 07:33:12 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8254</u> SIMN -	50.00		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	08/29/2015	Repaired	08/29/2015		
ESTHERVILLE SUB	<u>8268</u> SIMN -	75.00		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	08/29/2015	Repaired	08/29/2015		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.00		37.E3 -37.E3 - Vegetation brushi	Repaired Before Traffic	08/29/2015	Repaired	08/29/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 09/01/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 09/01/2015 05:01:23 PM

**Date Inspection Closed by Inspector:** 09/01/2015 04:51:58 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

#### Comments

DBI , Laurens MP 0 to mp 28.5 and Tara MP 44.5 to mp 32.95

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 09/04/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 09/04/2015 04:19:22 PM**Date Inspection Closed by Inspector:** 09/04/2015 04:15:32 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

Special Inspection, HOT Weather, Estherville Sub MP 78.4 to MP 32.25 . 87 degrees at 14:45

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.60		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	09/04/2015	Tightened frog bolt	09/04/2015		

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	71.21 71.21	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	09/04/2015	Installed bolt or bolts	09/04/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 09/05/2015    **Inspected By:** Gary Brockman

**Inspection Type:** FRA Required **Relief Inspector:** Data not entered  
**Weather:** Clear **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 09/05/2015 03:15:53 PM

**Date Inspection Closed by Inspector:** 09/05/2015 03:08:49 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

Special Inspection HOT Weather, Estherville MP 0 to MP 48.49. 89 degrees at 14:00 Hrs

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 09/08/2015 **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 09/08/2015 02:04:04 PM

**Date Inspection Closed by Inspector:** 09/08/2015 02:04:08 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	51.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	51.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

### Track Defects

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 09/11/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 09/11/2015 04:34:44 PM

**Date Inspection Closed by Inspector:** 09/11/2015 04:32:27 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02-002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02-001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02-767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02-767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	58.12		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/11/2015	Corr from Trk Mtce Plan	09/18/2015		
ESTHERVILLE SUB	8268 SIMN -	73.60		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/11/2015	Corr from Trk Mtce Plan	09/18/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02-001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 YARD	02-001	70.71	8268 YARD	02-005		
Walked	ESTHERVILLE SUB	8268 YARD	02-005	70.73	8268 YARD	02-002		
Walked	ESTHERVILLE SUB	8268 YARD	02-005	70.76	8268 YARD	02-004		
Walked	ESTHERVILLE SUB	8268 YARD	02-005	70.78	8268 INDU	02-761		
Walked	ESTHERVILLE SUB	8268 YARD	02-001	71.13	8268 YARD	02-005		

Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 YARD	02 - 503	71.38	8268 YARD	02 -502		
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP / User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	70.57 70.56		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	09/11/2015	Removed obstruction	09/11/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 09/12/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 09/12/2015 01:27:58 PM

**Date Inspection Closed by Inspector:** 09/12/2015 01:22:44 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	38.08		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/12/2015	Corr from Trk Mtce Plan	09/21/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 09/14/2015      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 09/14/2015 03:30:10 PM

**Date Inspection Closed by Inspector:** 09/14/2015 03:30:11 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 09/19/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 09/19/2015 03:48:32 PM

**Date Inspection Closed by Inspector:** 09/19/2015 03:46:18 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

		SIMN							
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	8.40 8.37		133A9-133.A9 - Loose or missing	Repaired Before Traffic	09/19/2015	Replaced adjustable rail braces	09/19/2015		
ESTHERVILLE SUB	8253 SIMN -	8.40 8.37		133A9-133.A9 - Loose or missing	Repaired Before Traffic	09/19/2015	Replaced adjustable rail braces	09/19/2015		
ESTHERVILLE SUB	8253 SIMN -	31.03 31.01		127A3-127.A3 - Insufficient fas	Repaired Before Traffic	09/19/2015	Installed additional fasteners	09/19/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

Inspection Date: 09/22/2015      Inspected By: Gary Brockman  
 Inspection Type: FRA Required      Relief Inspector: Data not entered  
 Weather: Clear      How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/22/2015 03:36:20 PM

Date Inspection Closed by Inspector: 09/22/2015 03:30:00 PM



### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

### Track Defects

No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.43 0.00		133AD-133.A13 - Loose, worn, or	Repaired Before Traffic	09/22/2015	Tightened guard rail bolt	09/22/2015		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 09/26/2015     **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required     **Relief Inspector:** Data not entered  
**Weather:** Clear     **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 09/26/2015 04:57:40 PM

**Date Inspection Closed by Inspector:** 09/26/2015 04:52:12 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

--	--	--	--	--	--	--	--	--	--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.05		121C2-121.C2 - Center cracked o	Repaired Before Traffic	09/26/2015	Replaced joint bars	09/26/2015		
ESTHERVILLE SUB	8253 SIMN	33.05		127A3-127.A3 - Insufficient fas	Repaired Before Traffic	09/26/2015	Installed additional fasteners	09/26/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	48.59 48.59		127A-127.A - Failure of fasten	Scheduled for Repair	09/26/2015	Corr from Trk Mtce Plan	10/23/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
		8254	-					

TWIN CITIES	ESTHERVILLE SUB	SIMN	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
-------------	-----------------	------	-------	-------	---------	---------	---------------------------

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 09/29/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 09/29/2015 03:56:38 PM

**Date Inspection Closed by Inspector:** 09/29/2015 03:52:03 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Comments									

#### Track Defects

No track defect records found

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 10/01/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/01/2015 03:41:35 PM

**Date Inspection Closed by Inspector:** 10/01/2015 03:37:04 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Track Traversed Information									
		8253	-						

TWIN CITIES	ESTHERVILLE SUB	SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	64.80		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/01/2015	Corr from Trk Mtce Plan	10/29/2015		
ESTHERVILLE SUB	8254 SIMN -	65.20		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/01/2015	Corr from Trk Mtce Plan	10/29/2015		
ESTHERVILLE SUB	8254 SIMN -	65.20		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/01/2015	Corr from Trk Mtce Plan	10/29/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 10/06/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 10/06/2015 03:16:29 PM

**Date Inspection Closed by Inspector:** 10/06/2015 03:05:22 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments**

--

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 10/08/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/08/2015 03:49:42 PM

**Date Inspection Closed by Inspector:** 10/08/2015 03:40:03 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURL00	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURL00	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURL00	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURL00	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURL00	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURL00	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURL00	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURL00	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURL00	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	77.90	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/08/2015	Installed bolt or bolts	10/08/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.61 0.00	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/08/2015	Installed bolt or bolts	10/08/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 10/10/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/10/2015 01:44:51 PM

**Date Inspection Closed by Inspector:** 10/10/2015 01:43:26 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments****Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 10/13/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 10/13/2015 05:14:21 PM

Date Inspection Closed by Inspector: 10/13/2015 04:43:08 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	2.39		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/13/2015	Corr from Trk Mtce Plan	11/11/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/17/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 10/17/2015 03:33:00 PM

Date Inspection Closed by Inspector: 10/17/2015 03:19:08 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	78.21	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/17/2015	Installed bolt or bolts	10/17/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	10/17/2015	Tightened connecting rod fastener	10/17/2015		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 10/19/2015    **Inspected By:** Joel Babcock  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/19/2015 12:44:19 PM

**Date Inspection Closed by Inspector:** 10/19/2015 12:36:35 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG



## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

## Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.43		121C2-121.C2 - Center cracked o	Repaired Before Traffic	10/19/2015	Replaced joint bars	10/19/2015		

## Switch Defects

No switch defect records found

## Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

Union Pacific Railroad  
FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/23/2015	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 10/23/2015 02:51:24 PM

Date Inspection Closed by Inspector: 10/23/2015 02:51:24 PM

## Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

## Track Defects

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/27/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 10/27/2015 04:08:58 PM

Date Inspection Closed by Inspector: 10/27/2015 04:04:28 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments**

There has been NO TRAINS MP 58.25 to MP 70.10 Tara Sub Since Last Traversal

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**

## FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/28/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/28/2015 03:19:18 PM

**Date Inspection Closed by Inspector:** 10/28/2015 03:16:42 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77- 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02- 001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02- 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02- 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02- 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02- 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02- 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02- 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.40	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/28/2015	Installed bolt or bolts	10/28/2015		
ESTHERVILLE SUB	8253 SIMN	46.05	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/28/2015	Installed bolt or bolts	10/28/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 - 820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 - 820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 - 809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 - 269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 - 729		RBM Standard Point
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	70.71	8268 YARD	02 - 005		
Walked	ESTHERVILLE SUB	8268 YARD	02 - 001	71.13	8268 YARD	02 - 005		

### Switch Defects

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 10/31/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 10/31/2015 04:16:37 PM

Date Inspection Closed by Inspector: 10/31/2015 04:10:28 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments****Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	58.49	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/31/2015	Installed bolt or bolts	10/31/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/03/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/03/2015 03:57:37 PM**Date Inspection Closed by Inspector:** 11/03/2015 03:49:29 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Comments									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/04/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/04/2015 04:03:24 PM**Date Inspection Closed by Inspector:** 11/04/2015 03:55:40 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
		8254	02						

TWIN CITIES	ESTHERVILLE SUB	INDU	733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02-001	70.57	71.21	No	REISWIG	DEURLOO	CLASS.TR#1
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.38	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	11/04/2015	Installed bolt or bolts	11/04/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	78.42 78.43		133A9-133.A9 - Loose or missing	Repaired Before Traffic	11/04/2015	Tightened adjustable rail braces	11/04/2015		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	58.00	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 11/07/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 11/07/2015 03:02:31 PM

Date Inspection Closed by Inspector: 11/07/2015 02:59:56 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	59.50	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	59.50	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 CNRT 02 117	48.55		127A-127.A - Failure of fasten	Scheduled for Repair	11/07/2015	Corr from Trk Mtce Plan	12/01/2015		
ESTHERVILLE SUB	8254 CNRT 02 117	48.57		127A-127.A - Failure of fasten	Scheduled for Repair	11/07/2015	Corr from Trk Mtce Plan	11/30/2015		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	59.50	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 11/10/2015 Inspected By: Gary Brockman  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 11/11/2015 07:49:21 AM

Date Inspection Closed by Inspector: 11/10/2015 05:05:43 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									
Defects Noted on FRA Report # 109 Filed by Secora									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 11/11/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 11/12/2015 07:54:15 AM

Date Inspection Closed by Inspector: 11/11/2015 08:52:05 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Tara Sub MP 27.0 to Mp 0.40 , Special Inspection Severe Weather { Tornado Activity}									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found



## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 11/14/2015	Inspected By: Gary Brockman
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 11/14/2015 03:31:54 PM

Date Inspection Closed by Inspector: 11/14/2015 03:30:09 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Comments									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIDE 02 103	31.06	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	11/14/2015	Installed bolt or bolts	11/14/2015		

#### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/17/2015    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/17/2015 04:02:03 PM

**Date Inspection Closed by Inspector:** 11/17/2015 03:57:09 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Comments									
Tara Sub MP 58.25 to MP 70.10, There has been NO TRAINS Since last traversed									

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/19/2015    **Inspected By:** Joel Babcock  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/19/2015 02:53:50 PM

**Date Inspection Closed by Inspector:** 11/19/2015 02:43:37 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/20/2015      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/20/2015 02:26:57 PM

**Date Inspection Closed by Inspector:** 11/20/2015 02:26:57 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

snow cover

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	69.49		121.18 -121.18 - Loose joint bars	Repaired Before Traffic	11/20/2015	Installed bolt or bolts	11/20/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/21/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/21/2015 06:32:09 PM

**Date Inspection Closed by Inspector:** 11/21/2015 06:27:07 PM

**Tracks Inspected**

--	--	--	--	--	--	--	--	--	--	--

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
<b>Track Traversed Information</b>									
- NONE -									
<b>Comments</b>									
Tara Sub Inspections , Where Made under Waldschmidt Track Warrants # 6964 and # 6713									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	47.18 47.18		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	11/21/2015	Removed obstruction	11/21/2015		

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/23/2015      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/23/2015 02:59:28 PM

**Date Inspection Closed by Inspector:** 11/23/2015 02:59:28 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
snow cover									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 11/25/2015	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 11/25/2015 02:40:22 PM

**Date Inspection Closed by Inspector:** 11/25/2015 02:40:22 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	49.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	49.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									
olson covered 33-14									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/01/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 12/01/2015 04:33:38 PM

**Date Inspection Closed by Inspector:** 12/01/2015 04:24:01 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
--------------	-------------	------------------	----------------	-------------	-----------	----------	---------	-------------------

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/04/2015	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 12/04/2015 02:54:17 PM

**Date Inspection Closed by Inspector:** 12/04/2015 02:54:17 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

snow cover

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	58.46		121.13 -121.13 - Cracked or broke	Repaired Before Traffic	12/04/2015	Replaced joint bars	12/04/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/05/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/05/2015 01:19:55 PM

**Date Inspection Closed by Inspector:** 12/05/2015 01:12:37 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	ZZ 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)

TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	53.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	53.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.60		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	12/05/2015	Tightened frog bolt	12/05/2015		
ESTHERVILLE SUB	8254 SIMN -	48.60		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	12/05/2015	Tightened frog bolt	12/05/2015		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/08/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 12/08/2015 03:51:29 PM

**Date Inspection Closed by Inspector:** 12/08/2015 03:44:21 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**



No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/09/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 12/09/2015 04:31:42 PM

Date Inspection Closed by Inspector: 12/09/2015 04:24:10 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments****Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	71.54		119C-119.C - Failure to comply	Scheduled for Repair	12/09/2015	Corr from Trk Mtce Plan	01/08/2016		
ESTHERVILLE SUB	8254 SIMN -	69.37		121C2-121.C2 - Center cracked o	Repaired Before Traffic	12/09/2015	Replaced joint bars	12/09/2015		

ESTHERVILLE SUB	8268 SIMN -	71.54		121C2-121.C2 - Center cracked o	Repaired Before Traffic	12/09/2015	Replaced joint bars	12/09/2015		
-----------------	-------------------	-------	--	---------------------------------	-------------------------	------------	---------------------	------------	--	--

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	REISWIG	DEURLOO	SUPERIOR COOP

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/11/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 12/11/2015 05:23:46 PM

**Date Inspection Closed by Inspector:** 12/11/2015 05:14:25 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Comments

--

### Track Defects

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 12/12/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/12/2015 01:28:07 PM

**Date Inspection Closed by Inspector:** 12/12/2015 01:25:27 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 12/14/2015      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 12/14/2015 03:21:05 PM

**Date Inspection Closed by Inspector:** 12/14/2015 03:21:05 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

SIMN									
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/15/2015	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/15/2015 02:52:18 PM

**Date Inspection Closed by Inspector:** 12/15/2015 02:49:48 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	78.00	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	12/15/2015	Installed bolt or bolts	12/15/2015		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.61 0.00	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	12/15/2015	Installed bolt or bolts	12/15/2015		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/17/2015	<b>Inspected By:</b> Kyle Olson
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Kyle Olson
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 12/17/2015 02:51:53 PM

Date Inspection Closed by Inspector: 12/17/2015 02:51:53 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG

**Comments****Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/21/2015      **Inspected By:** Kyle Olson  
**Inspection Type:** FRA Required      **Relief Inspector:** Kyle Olson  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 12/21/2015 07:56:18 PM

**Date Inspection Closed by Inspector:** 12/21/2015 07:56:18 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									
sweet									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	40.20	Defect Length : 1	113BD-113.B13 - Bolt-hole crack	Repaired Before Traffic	12/21/2015	Replaced Rail	12/21/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/26/2015      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 12/26/2015 04:31:16 PM

**Date Inspection Closed by Inspector:** 12/26/2015 04:21:59 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253	02	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

		SIDE	103						
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

Inspection Date: 12/28/2015    Inspected By: Gary Brockman  
 Inspection Type: FRA Required    Relief Inspector: Data not entered  
 Weather: Clear    How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 12/28/2015 02:02:15 PM

Date Inspection Closed by Inspector: 12/28/2015 01:53:18 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

Estherville Sub MP 45.0 to MP 78.40 , Inspected By Kyle Olsen, Foreman, Tara Sub MP 58.25 to MP 40.0 Inspected DR Dickey Foreman

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	71.17		121C2-121.C2 - Center cracked o	Repaired Before Traffic	12/28/2015	Replaced joint bars	12/28/2015		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/02/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 01/02/2016 03:44:43 PM

**Date Inspection Closed by Inspector:** 01/02/2016 03:43:06 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Comments

### Track Defects

No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone /	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------	-------------	--------------------	------------------	-----------------	----------------------	-------------------	-----------------------	---------	----------



Track									
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>46.11</u> 46.11		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/02/2016	Removed obstruction	01/02/2016	
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>47.16</u> 47.16		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/02/2016	Removed obstruction	01/02/2016	

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 01/04/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 01/05/2016 06:54:56 AM

**Date Inspection Closed by Inspector:** 01/05/2016 06:54:56 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		44.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		44.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 01/06/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/06/2016 03:57:29 PM

**Date Inspection Closed by Inspector:** 01/06/2016 03:47:52 PM

**Tracks Inspected**

						Rail			
--	--	--	--	--	--	------	--	--	--

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									
Snow covered tracks									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/07/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 01/07/2016 04:46:07 PM

Date Inspection Closed by Inspector: 01/07/2016 04:36:02 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.61 0.00	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	01/07/2016	Installed bolt or bolts	01/07/2016		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 01/09/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/09/2016 05:16:34 PM**Date Inspection Closed by Inspector:** 01/09/2016 05:14:31 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Comments									
Special Inspection Cold Weather, MP 0 to MP 60									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 01/12/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 01/12/2016 05:35:46 PM**Date Inspection Closed by Inspector:** 01/12/2016 05:29:03 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	20.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	20.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	--------------	---	------	-------	----	---------	---------	-------------------------

#### Comments

Tara Sub MP 32.95 to MP 58.25 And Estherville Sub MP 0 to MP 20 Special Inspection Cold Weather. NO trains Tara Sub MP 58.25 to MP 70.10 Since Last traversed and Inspected

#### Track Defects

No track defect records found

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/13/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/13/2016 04:48:00 PM

**Date Inspection Closed by Inspector:** 01/13/2016 04:39:02 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

#### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	27.13 27.11		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/13/2016	Removed obstruction	01/13/2016		
ESTHERVILLE SUB	8253 SIMN -	27.13 27.11		133AH-133.A17 - Obstruction in	Repaired Before Traffic	01/13/2016	Removed obstruction	01/13/2016		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 01/16/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/16/2016 03:17:21 PM

**Date Inspection Closed by Inspector:** 01/16/2016 03:06:39 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

SIMN
<b>Comments</b>
MP 0 TO MP 60.0 , Special Inspection Cold Weather

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	8.40 8.37		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/16/2016	Removed obstruction	01/16/2016		
ESTHERVILLE SUB	8253 SIMN	46.11 46.11		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/16/2016	Removed obstruction	01/16/2016		

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 01/18/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 01/18/2016 04:32:08 PM

**Date Inspection Closed by Inspector:** 01/18/2016 04:32:08 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

snow cover

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
	8268									

ESTHERVILLE SUB	SIMN	72.31	Number of Bolts : 2	121E-121.E - Less than 2 bolts	Repaired Before Traffic	01/18/2016	Installed bolt or bolts	01/18/2016		
-----------------	------	-------	---------------------	--------------------------------	-------------------------	------------	-------------------------	------------	--	--

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/19/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 01/19/2016 04:21:54 PM

Date Inspection Closed by Inspector: 01/19/2016 04:19:03 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

Special Inspection, Cold Weather , Tara Sub MP 32.95 to MP 58.25 and Estherville Sub MP 0.0 to MP 48.49 Tara Sub MP 58.25 to MP 70.10 , NO TRAINS Since Last Inspected

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/20/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/20/2016 03:22:00 PM

**Date Inspection Closed by Inspector:** 01/20/2016 03:11:39 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.41	78.43	No	?	?	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

Special Inspection Cold Weather MP 48.49 to MP 31

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone /	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------------	----------------	-----------------------	------------------	--------------------	-------------------------	----------------------	--------------------------	---------	----------



Track									
ESTHERVILLE SUB	<u>8254</u> SIMN -	<u>48.95</u> 48.95		205C1-205.C1 - Loose, worn, or	Repaired Before Traffic	01/20/2016	Replaced	01/20/2016	
ESTHERVILLE SUB	<u>8254</u> SIMN -	<u>59.43</u> 59.43		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/20/2016	Removed obstruction	01/20/2016	
ESTHERVILLE SUB	<u>8254</u> SIMN -	<u>58.50</u> 58.50		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/20/2016	Removed obstruction	01/20/2016	
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>46.11</u> 46.11		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/20/2016	Removed obstruction	01/20/2016	

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/23/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/23/2016 02:42:08 PM

**Date Inspection Closed by Inspector:** 01/23/2016 02:38:52 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8254</u> SIMN -	48.60		133AH-133.A17 - Obstruction in	Repaired Before Traffic	01/23/2016	Removed obstruction	01/23/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 01/27/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Dustin Dickey  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 01/28/2016 06:57:19 AM

**Date Inspection Closed by Inspector:** 01/28/2016 06:57:20 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 01/30/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 01/30/2016 03:27:38 PM

**Date Inspection Closed by Inspector:** 01/30/2016 03:21:06 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253	02	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

		SIDE	103						
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Tara Sub MP 58.25 to MP 70.10, NO TRAINS since Last Inspected And Traversed									

**Track Defects**  
No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	47.18 47.18	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	01/30/2016	Installed bolt or bolts	01/30/2016		

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 02/03/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/04/2016 07:55:58 AM

**Date Inspection Closed by Inspector:** 02/03/2016 06:37:55 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									
Snow Covered Tracks									

**Track Defects**  
No track defect records found

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 02/04/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 02/04/2016 04:05:50 PM

**Date Inspection Closed by Inspector:** 02/04/2016 04:01:31 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Snow Covered Tracks									

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	58.50 58.50		135H1-135.H1 - Unusually chippe	Scheduled for Repair	02/04/2016	Corr from Trk Mtce Plan	03/04/2016		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 02/06/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 02/06/2016 04:46:23 PM

**Date Inspection Closed by Inspector:** 02/06/2016 04:38:52 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
--------------	-------------	------------------	----------------	-------------	-----------	----------------------	----------	---------	-------------------

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
Snow covered tracks									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 02/09/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/09/2016 02:43:48 PM

**Date Inspection Closed by Inspector:** 02/09/2016 02:36:57 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	47.50	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	47.50	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	27.84 27.82		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/09/2016	Removed obstruction	02/09/2016		
ESTHERVILLE SUB	8253 SIMN -	27.13 27.11		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/09/2016	Removed obstruction	02/09/2016		

**Joint Bar Inspections**

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/13/2016	Inspected By: Gary Brockman
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 02/13/2016 06:15:25 PM

Date Inspection Closed by Inspector: 02/13/2016 06:06:27 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									
Complete Traversal of the Laurens Sub was Incomplete, Because Heavy Flange / Drifted Snow at Various Locations, Heavy Snow Drifts and Flange Ways On Estherville Sub Also									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.59		133AH-133.A17 - Obstruction in	Repaired Before Traffic	02/13/2016	Removed obstruction	02/13/2016		

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/16/2016	Inspected By: Gary Brockman
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 02/16/2016 04:07:17 PM

Date Inspection Closed by Inspector: 02/16/2016 04:05:44 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

MP 60.0 to MP 50 .0 , Inspected under D R Dickey Trk Warrant

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/16/2016	Removed obstruction	02/16/2016		
ESTHERVILLE SUB	8254 SIMN -	59.43 59.43		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/16/2016	Removed obstruction	02/16/2016		
ESTHERVILLE SUB	8254 SIMN -	58.50 58.50		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/16/2016	Removed obstruction	02/16/2016		

### Joint Bar Inspections

--	--	--	--	--	--	--	--	--	--	--

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 02/18/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 02/18/2016 05:12:18 PM

**Date Inspection Closed by Inspector:** 02/18/2016 05:12:19 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

snow cover

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	31.03	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/18/2016	Installed bolt or bolts	02/18/2016		
ESTHERVILLE SUB	8254 SIMN	59.69	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/18/2016	Installed bolt or bolts	02/18/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**



## FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/23/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 02/23/2016 04:19:14 PM

**Date Inspection Closed by Inspector:** 02/23/2016 04:19:14 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Comments

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/23/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> DR Dickey
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/24/2016 09:03:11 AM

**Date Inspection Closed by Inspector:** 02/23/2016 03:59:56 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.55	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.55	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

### Track Defects

No track defect records found

## Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

## Switch Defects

No switch defect records found

## Joint Bar Inspections

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.55	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

Union Pacific Railroad  
FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/26/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> D R Dickey
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 02/26/2016 03:34:48 PM

Date Inspection Closed by Inspector: 02/26/2016 03:06:56 PM

## Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.95 48.95		133A7-133.A7 - Worn or missing	Repaired Before Traffic	02/26/2016	Replaced cotter pins	02/26/2016		
ESTHERVILLE SUB	8254 SIMN -	48.95 48.95		133A7-133.A7 - Worn or missing	Repaired Before Traffic	02/26/2016	Replaced cotter pins	02/26/2016		
ESTHERVILLE SUB	8254 SIMN -	48.95 48.95		133A7-133.A7 - Worn or missing	Repaired Before Traffic	02/26/2016	Replaced cotter pins	02/26/2016		
ESTHERVILLE SUB	8254 SIMN -	59.43 59.43		135D-135.D - Heel of switch in	Repaired Before Traffic	02/26/2016	Replaced heel block bolt	02/26/2016		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 03/01/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 03/01/2016 03:08:04 PM

**Date Inspection Closed by Inspector:** 03/01/2016 03:08:04 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/	Zone/	Begin	End	Rail Xing	Director	Manager	Track Description
--------------	-------------	------	-------	-------	-----	-----------	----------	---------	-------------------

		Trk Type	Track	MP	MP	Insp			
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
snow cover									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/01/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 03/01/2016 03:25:37 PM

Date Inspection Closed by Inspector: 03/01/2016 03:25:37 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/04/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> D R Dickey
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/04/2016 03:30:28 PM

**Date Inspection Closed by Inspector:** 03/04/2016 03:21:16 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	70.55	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	70.55	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.32	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	03/04/2016	Installed bolt or bolts	03/04/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese

Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmetsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmetsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmetsburg AGP	Spring-All Rail Extd length

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.27 32.26		121C2-121.C2 - Center cracked o	Repaired Before Traffic	03/04/2016	Replaced joint bars	03/04/2016		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	70.55	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 03/08/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 03/08/2016 04:12:54 PM

**Date Inspection Closed by Inspector:** 03/08/2016 04:12:54 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 03/08/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** DR Dickey  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/08/2016 12:50:44 PM

**Date Inspection Closed by Inspector:** 03/08/2016 12:43:13 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	77.74 77.75		121C1-121.C1 - Center cracked o	Remove From Service	03/08/2016	Corr from Trk Mtce Plan	04/20/2016		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 03/11/2016    **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 03/11/2016 03:23:06 PM

**Date Inspection Closed by Inspector:** 03/11/2016 02:48:56 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
- N O N E -									
<b>Comments</b>									

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 03/15/2016    **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 03/15/2016 03:18:06 PM

**Date Inspection Closed by Inspector:** 03/15/2016 03:08:38 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	Yes	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	Yes	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE



TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.01		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/15/2016	Corr from Trk Mtce Plan	04/13/2016		
ESTHERVILLE SUB	8254 SIMN -	69.02		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/15/2016	Corr from Trk Mtce Plan	04/13/2016		
ESTHERVILLE SUB	8254 SIMN -	69.07		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/15/2016	Corr from Trk Mtce Plan	04/12/2016		
ESTHERVILLE SUB	8268 SIMN -	71.35		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/15/2016	Corr from Trk Mtce Plan	04/12/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/17/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail

**Date Inspection Uploaded into the Central System:** 03/17/2016 02:15:51 PM

**Date Inspection Closed by Inspector:** 03/17/2016 02:03:34 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 03/22/2016      **Inspected By:** JASON Waldschmidt  
**Inspection Type:** FRA Required      **Relief Inspector:** Jason Waldschmidt  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 03/22/2016 04:16:38 PM

**Date Inspection Closed by Inspector:** 03/22/2016 04:16:38 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 03/24/2016      **Inspected By:** Kyle Olson  
**Inspection Type:** FRA Required      **Relief Inspector:** Kyle Olson  
**Weather:** Data not entered      **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/24/2016 03:24:13 PM  
 Date Inspection Closed by Inspector: 03/24/2016 03:24:14 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Comments									
snow covered									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
 FRA Track Inspection & Defect Report**

Inspection Date: 03/29/2016 Inspected By: Dustin Dickey  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 03/29/2016 02:47:48 PM  
 Date Inspection Closed by Inspector: 03/29/2016 02:36:41 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
	8254									

ESTHERVILLE SUB	<u>SIMN</u> -	61.07		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/29/2016	Corr from Trk Mtce Plan	04/27/2016		
ESTHERVILLE SUB	<u>8254 SIMN</u> -	61.15		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/29/2016	Corr from Trk Mtce Plan	04/27/2016		
ESTHERVILLE SUB	<u>8254 SIMN</u> -	68.06		109B2-109.B2 - Crossties not ef	Repaired Before Traffic	03/29/2016	Repaired	03/29/2016		
ESTHERVILLE SUB	<u>8254 SIMN</u> -	68.08		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/29/2016	Repaired	03/29/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/31/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 03/31/2016 02:44:40 PM

**Date Inspection Closed by Inspector:** 03/31/2016 02:34:52 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8254 CROS</u>	<u>77</u> 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	<u>8253 SIDE</u>	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253 SIMN</u>	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254 YARD</u>	<u>02</u> 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	<u>8254 CNRT</u>	<u>02</u> 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	<u>8254 YARD</u>	<u>02</u> 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	<u>8253 SIMN</u>	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253 SIDE</u>	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Comments

--

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	<u>8254 YARD</u>	02 - 729	48.64	<u>8254 CROS</u>	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	<u>8254 YARD</u>	02 - 730	48.73	<u>8254 YARD</u>	02 -729		RBM Standard Point

### Switch Defects

No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 04/05/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 04/05/2016 03:30:42 PM  
**Date Inspection Closed by Inspector:** 04/05/2016 03:27:12 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	Yes	REISWIG	DEURLOO	AG PARTNERS

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	0.25		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/05/2016	Corr from Trk Mtce Plan	04/27/2016		
ESTHERVILLE SUB	8253 SIMN	32.43		121F1-121.F1 - Loose joint bars	Repaired Before Traffic	04/05/2016	Tightened joint bars	04/05/2016		
ESTHERVILLE SUB	8253 SIMN	32.30		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/05/2016	Tightened joint bars	04/05/2016		
ESTHERVILLE SUB	8253 SIMN	32.30		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/05/2016	Tightened joint bars	04/05/2016		

ESTHERVILLE SUB	8253 SIMN	32.45		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/05/2016	Tightened joint bars	04/05/2016		
-----------------	--------------	-------	--	---------------------------------	-------------------------	------------	----------------------	------------	--	--

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmetsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/09/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 04/09/2016 01:52:03 PM

**Date Inspection Closed by Inspector:** 04/09/2016 01:47:18 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	--------------	---	------	-------	----	---------	---------	-------------------------

### Comments

--

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 04/12/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/12/2016 05:26:28 PM**Date Inspection Closed by Inspector:** 04/12/2016 05:24:17 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

		SIMN							
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	45.28		121F1-121.F1 - Loose joint bars	Repaired Before Traffic	04/12/2016	Installed bolt or bolts	04/12/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 04/16/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 04/16/2016 01:06:10 PM

**Date Inspection Closed by Inspector:** 04/16/2016 01:00:57 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	31.04		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/16/2016	Installed bolt or bolts	04/16/2016		



ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	33.01		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/16/2016	Installed bolt or bolts	04/16/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	33.01		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/16/2016	Installed bolt or bolts	04/16/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	33.50		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	04/16/2016	Tightened joint bars	04/16/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIDE</u> <u>02</u> <u>103</u>	32.16		127A3-127.A3 - Insufficient fas	Scheduled for Repair	04/16/2016	Corr from Trk Mtce Plan	05/16/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIDE</u> <u>02</u> <u>103</u>	32.16		127A3-127.A3 - Insufficient fas	Repaired Before Traffic	04/16/2016	Repaired	04/16/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 04/19/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/19/2016 03:54:15 PM

**Date Inspection Closed by Inspector:** 04/19/2016 03:52:47 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> YARD	<u>02</u> 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> YARD	<u>02</u> 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> INDU	<u>02</u> 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> INDU	<u>02</u> 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> YARD	<u>02</u> 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> CNRT	<u>02</u> 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> YARD	<u>02</u> 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> CROS	<u>77</u> 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> YARD	<u>02</u> 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> INDU	<u>02</u> 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> INDU	<u>02</u> 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP

TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	42.50		109B2-109.B2 - Crossties not ef	Scheduled for Repair	04/19/2016	Corr from Trk Mtce Plan	05/19/2016		
ESTHERVILLE SUB	8254 SIMN -	69.40		121B2-121.B2 - Cracked or broke	Repaired Before Traffic	04/19/2016	Replaced joint bars	04/19/2016		
ESTHERVILLE SUB	8254 SIMN -	69.62		121F1-121.F1 - Loose joint bars	Repaired Before Traffic	04/19/2016	Installed bolt or bolts	04/19/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 04/23/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/23/2016 01:28:55 PM

**Date Inspection Closed by Inspector:** 04/23/2016 01:18:23 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 04/26/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 04/26/2016 04:27:07 PM

**Date Inspection Closed by Inspector:** 04/26/2016 04:17:20 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 YARD 02 724	33.50		135.E2 -135.E2 - Connecting rod i	Repaired Before Traffic	04/26/2016	Repaired	04/26/2016		
ESTHERVILLE SUB	8268 SIMN -	76.65	Deviation Profile : <b>2</b>	63A2-63.A2 - Deviation from un	Repaired Before Traffic	04/26/2016	Tamped to Surface Track	04/26/2016		
ESTHERVILLE SUB	8253 SIMN	34.88	Deviation Zero : <b>1.5</b>	63A3-63.A3 - Deviation from ze	Repaired Before Traffic	04/26/2016	Tamped to Surface Track	04/26/2016		
ESTHERVILLE SUB	8268 SIMN -	75.40	Deviation Zero : <b>2.625</b>	63A3-63.A3 - Deviation from ze	213.9B	04/26/2016	Corr from Trk Mtce Plan	04/27/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 04/30/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 04/30/2016 01:12:46 PM

**Date Inspection Closed by Inspector:** 04/30/2016 01:07:35 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.30		137E-137.E - Severe frog condi	Scheduled for Repair	04/30/2016	Corr from Trk Mtce Plan	05/27/2016		
ESTHERVILLE SUB	8253 SIMN	32.44		137E-137.E - Severe frog condi	Scheduled for Repair	04/30/2016	Corr from Trk Mtce Plan	05/27/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 05/04/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 05/04/2016 06:18:57 PM

**Date Inspection Closed by Inspector:** 05/04/2016 06:07:07 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253	02	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

		YARD	724						
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	17.41		123B-123.B - Object between ba	Repaired Before Traffic	05/04/2016	Removed objects between base of rail and tie plate	05/04/2016		
ESTHERVILLE SUB	8253 SIMN -	8.40	Gap Witdh : <b>0.125</b>	135B1-135.B1 - Improper fit bet	Repaired Before Traffic	05/04/2016	Repaired	05/04/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 05/06/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 05/06/2016 04:17:24 PM

**Date Inspection Closed by Inspector:** 05/06/2016 04:16:28 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	59.40		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/06/2016	Installed bolt or bolts	05/06/2016		
ESTHERVILLE SUB	8254 SIMN -	59.40		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/06/2016	Installed bolt or bolts	05/06/2016		
ESTHERVILLE SUB	8254 SIMN -	59.41		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/06/2016	Tightened joint bars	05/06/2016		
ESTHERVILLE SUB	8254 SIMN -	69.61		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/06/2016	Installed bolt or bolts	05/06/2016		
ESTHERVILLE SUB	8254 SIMN -	69.62		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/06/2016	Installed bolt or bolts	05/06/2016		
ESTHERVILLE SUB	8254 SIMN -	69.62		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/06/2016	Installed bolt or bolts	05/06/2016		
ESTHERVILLE SUB	8268 SIMN -	70.56		135D-135.D - Heel of switch in	Scheduled for Repair	05/06/2016	Corr from Trk Mtce Plan	05/19/2016		
ESTHERVILLE SUB	8254 SIMN -	48.95		135H1-135.H1 - Unusually chippe	Remove From Service	05/06/2016	Corr from Trk Mtce Plan	01/06/2017		

## Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

## Switch Defects

No switch defect records found

## Joint Bar Inspections

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	REISWIG	DEURLOO	SUPERIOR COOP

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

Union Pacific Railroad  
FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 05/07/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

Date Inspection Uploaded into the Central System: 05/07/2016 12:15:58 PM

Date Inspection Closed by Inspector: 05/07/2016 08:59:31 AM

## Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
		8253	02						



TWIN CITIES	ESTHERVILLE SUB	INDU	711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	REISWIG	DEURLOO	GOLD EAGLE COOP

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

Inspection Date: 05/10/2016 Inspected By: Gabriel Navarrete  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 05/10/2016 03:22:44 PM

Date Inspection Closed by Inspector: 05/10/2016 03:11:29 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.58	Number of Non-Defective Crossties : 2	109BB-109.B1ii - 39-foot segmen	Slow Order to 10 mph	05/10/2016	Corr from Trk Mtce Plan	05/12/2016		
ESTHERVILLE SUB	8254 SIMN -	48.59	Number of Non-Defective Crossties : 2	109BB-109.B1ii - 39-foot segmen	Slow Order to 10 mph	05/10/2016	Corr from Trk Mtce Plan	05/12/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
		8253	02					

TWIN CITIES	ESTHERVILLE SUB	INDU	723	32.27	32.40	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	REISWIG	DEURLOO	GOLD EAGLE COOP

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 05/10/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 05/10/2016 03:22:46 PM

**Date Inspection Closed by Inspector:** 05/10/2016 03:22:13 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	REISWIG	DEURLOO	AG PARTNERS

TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	REISWIG	DEURLOO	SUPERIOR COOP

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 05/14/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/14/2016 03:36:34 PM

**Date Inspection Closed by Inspector:** 05/14/2016 03:23:37 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

--

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 05/18/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/18/2016 02:34:39 PM  
**Date Inspection Closed by Inspector:** 05/18/2016 02:25:24 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 05/19/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/19/2016 03:47:41 PM  
**Date Inspection Closed by Inspector:** 05/19/2016 03:38:48 PM

### Tracks Inspected

		Seg/	Zone/	Begin	End	Rail			

Service Unit	Subdivision	Trk Type	Track	MP	MP	Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 05/21/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/21/2016 01:00:59 PM

**Date Inspection Closed by Inspector:** 05/21/2016 12:51:17 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
		8253	02						

TWIN CITIES	ESTHERVILLE SUB	INDU	820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 05/24/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/24/2016 02:26:44 PM

**Date Inspection Closed by Inspector:** 05/24/2016 02:21:34 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77. 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02. 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
mp 50 -mp 78.4 inspected by dave deurloo									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	48.52		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/24/2016	Installed bolt or bolts	05/24/2016		
ESTHERVILLE SUB	8254 SIMN -	48.52		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/24/2016	Installed bolt or bolts	05/24/2016		
ESTHERVILLE SUB	8254 SIMN -	48.52		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/24/2016	Installed bolt or bolts	05/24/2016		
ESTHERVILLE SUB	8254 SIMN -	48.52		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/24/2016	Installed bolt or bolts	05/24/2016		
ESTHERVILLE SUB	8254 SIMN -	48.52		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	05/24/2016	Installed bolt or bolts	05/24/2016		
ESTHERVILLE SUB	8253 SIMN	35.07	Deviation Profile : 2.125	63A2-63.A2 - Deviation from un	Repaired Before Traffic	05/24/2016	Tamped to Surface Track	05/24/2016		

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	70.56 70.55		127A-127.A - Failure of fasten	Scheduled for Repair	05/24/2016	Corr from Trk Mtce Plan	06/21/2016		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 05/28/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/28/2016 01:10:40 PM

**Date Inspection Closed by Inspector:** 05/28/2016 01:04:25 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/	Zone/	Begin	End	Rail Xing	Director	Manager	Track Description
--------------	-------------	------	-------	-------	-----	-----------	----------	---------	-------------------



		Trk Type	Track	MP	MP	Insp			
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.00		121B2-121.B2 - Cracked or broke	Repaired Before Traffic	05/28/2016	Replaced joint bars	05/28/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 05/31/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 05/31/2016 02:15:27 PM

**Date Inspection Closed by Inspector:** 05/31/2016 02:05:39 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
		8253	02						

TWIN CITIES	ESTHERVILLE SUB	YARD	724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	REISWIG	DEURLOO	GOLD EAGLE COOP

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/01/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/01/2016 04:44:37 PM

**Date Inspection Closed by Inspector:** 06/01/2016 04:37:07 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	57.64		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/29/2016		
ESTHERVILLE SUB	8254 SIMN -	58.24		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/28/2016		

ESTHERVILLE SUB	<u>8254</u> SIMN -	58.27		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/24/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.29		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/28/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.30		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/24/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.32		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/14/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.80		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/23/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.90		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/21/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	57.64		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/29/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.24		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/28/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.27		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/24/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.29		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/28/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.30		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/24/2016		
ESTHERVILLE SUB	<u>8254</u> SIMN -	58.32		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/14/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.52		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/10/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.52		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/10/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.75		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/10/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.80		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/23/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.81		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/15/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.90		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/23/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	72.14		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/10/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	73.69		127A-127.A - Failure of fasten	Scheduled for Repair	06/01/2016	Corr from Trk Mtce Plan	06/21/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	71.54	Gage Measurement : <b>57.75</b>	53B3-53.B3 - Gage dimension on	Repaired Before Traffic	06/01/2016	Gaged track	06/01/2016		
ESTHERVILLE SUB	<u>8268</u> SIMN -	73.06	Gage Measurement : <b>57.75</b>	53B3-53.B3 - Gage dimension on	Repaired Before Traffic	06/01/2016	Gaged track	06/01/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	<u>8254</u> SIMN	-	48.59	<u>8254</u> CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	<u>8254</u> SIMN	-	48.95	<u>8254</u> YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	<u>8254</u> SIMN	-	58.5	<u>8254</u> INDU	02 -732	Greattinger Elevator	RBM Standard Point

Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	REISWIG	DEURLOO	SUPERIOR COOP

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 06/04/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/04/2016 03:30:38 PM

**Date Inspection Closed by Inspector:** 06/04/2016 03:24:26 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253	02	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING

Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	32.17		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/04/2016	Tightened joint bars	06/04/2016		
ESTHERVILLE SUB	8253 SIMN -	32.18		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/04/2016	Installed bolt or bolts	06/04/2016		
ESTHERVILLE SUB	8253 SIMN	32.42		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/04/2016	Tightened joint bars	06/04/2016		
ESTHERVILLE SUB	8253 SIMN	32.44		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/04/2016	Installed bolt or bolts	06/04/2016		
ESTHERVILLE SUB	8253 SIMN	32.45		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/04/2016	Tightened joint bars	06/04/2016		
ESTHERVILLE SUB	8253 SIMN	32.45		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/04/2016	Installed bolt or bolts	06/04/2016		
ESTHERVILLE SUB	8253 SIMN -	8.41	Gap Withd : <b>0.125</b>	135B1-135.B1 - Improper fit bet	Scheduled for Repair	06/04/2016	Corr from Trk Mtce Plan	06/30/2016		
ESTHERVILLE SUB	8253 SIMN -	4.03	Deviation Profile : <b>1.25</b>	63A2-63.A2 - Deviation from un	Repaired Before Traffic	06/04/2016	Tamped to Surface Track	06/04/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 06/07/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/08/2016 07:19:01 AM

**Date Inspection Closed by Inspector:** 06/07/2016 03:06:19 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL

TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77-269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02-730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02-767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02-729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02-733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02-767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02-767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02-733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02-002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02-732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02-767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02-724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02-809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02-732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

--	--	--	--	--	--	--	--	--	--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	74.50	Deviation Zero : <b>1.9375</b>	103D-103.D - Fouled or insuffi	Scheduled for Repair	06/07/2016	Corr from Trk Mtce Plan	06/23/2016		
ESTHERVILLE SUB	8253 SIMN -	9.17		135H1-135.H1 - Unusually chippe	Remove From Service	06/07/2016	Repaired	06/09/2016		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268	-	70.56	8267	-	Rake Junction Switch	RBM Standard Point

		SIMN			SIMN			
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	REISWIG	DEURLOO	SUPERIOR COOP

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 06/09/2016	<b>Inspected By:</b> David Deurloo
<b>Inspection Type:</b> Special	<b>Relief Inspector:</b> David Deurloo
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 06/18/2016 09:35:53 AM

**Date Inspection Closed by Inspector:** 06/18/2016 09:35:54 AM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	0.15	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		48.41	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	48.54	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	0.15	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		48.41	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	48.54	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

Walked the only lagged curve on this territory at Moorland MP 0.034-0.104 on the Fort Dodge Sub. All the other curves listed on the Estherville Sub., Jewell Sub., Laurens Sub. and the Waterloo Ind. Lead have regular ties plates and cut spikes. Not sure of why there is all this bad curve data?

### Track Defects

No track defect records found



**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/09/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/09/2016 02:31:12 PM

**Date Inspection Closed by Inspector:** 06/09/2016 07:50:44 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
<b>Track Traversed Information</b>									
- N O N E -									
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 INDU 02 711	9.17		135H1-135.H1 - Unusually chippe	Remove From Service	06/09/2016				

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/10/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/10/2016 12:13:48 PM

**Date Inspection Closed by Inspector:** 06/10/2016 11:59:39 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	30.05	Deviation Profile : 2	63A2-63.A2 - Deviation from un	Repaired Before Traffic	06/10/2016	Tamped to Surface Track	06/10/2016		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/14/2016      **Inspected By:** JASON Waldschmidt  
**Inspection Type:** FRA Required      **Relief Inspector:** Jason Waldschmidt  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 06/14/2016 04:40:05 PM  
**Date Inspection Closed by Inspector:** 06/14/2016 04:40:06 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/16/2016      **Inspected By:** JASON Waldschmidt  
**Inspection Type:** FRA Required      **Relief Inspector:** Jason Waldschmidt  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 06/16/2016 02:56:12 PM  
**Date Inspection Closed by Inspector:** 06/16/2016 02:56:12 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
		8253	02						

TWIN CITIES	ESTHERVILLE SUB	SIDE	103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	42.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	42.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 06/16/2016	<b>Inspected By:</b> Joel Babcock
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/16/2016 03:26:47 PM

**Date Inspection Closed by Inspector:** 06/16/2016 03:17:34 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	22.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	22.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
mtm and fra all defects noted in fra inspection									

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	22.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 06/21/2016	<b>Inspected By:</b> Gabriel Navarrete
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 06/21/2016 02:46:52 PM

Date Inspection Closed by Inspector: 06/21/2016 02:38:17 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments****Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 06/24/2016    **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/24/2016 02:43:51 PM

**Date Inspection Closed by Inspector:** 06/24/2016 02:39:55 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL

#### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

--	--	--	--	--	--	--	--	--	--

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	71.84		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/24/2016	Corr from Trk Mtce Plan	07/15/2016		
ESTHERVILLE SUB	8268 SIMN -	73.10		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/24/2016	Corr from Trk Mtce Plan	07/15/2016		
ESTHERVILLE SUB	8268 SIMN -	73.11		109B2-109.B2 - Crossties not ef	Scheduled for Repair	06/24/2016	Corr from Trk Mtce Plan	07/21/2016		

#### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point

#### Switch Defects

--	--	--	--	--	--	--	--	--	--

No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/25/2016      **Inspected By:** Gabriel Navarrete  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 06/25/2016 01:37:47 PM

**Date Inspection Closed by Inspector:** 06/25/2016 01:33:28 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 06/28/2016      **Inspected By:** JASON Waldschmidt  
**Inspection Type:** FRA Required      **Relief Inspector:** Jason Waldschmidt  
**Weather:** Data not entered      **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 06/28/2016 03:14:39 PM

Date Inspection Closed by Inspector: 06/28/2016 03:14:39 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02/103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	52.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02/103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	52.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

--

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 06/29/2016	Inspected By: JASON Waldschmidt
Inspection Type: FRA Required	Relief Inspector: Jason Waldschmidt
Weather: Data not entered	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 06/29/2016 04:34:50 PM

Date Inspection Closed by Inspector: 06/29/2016 04:34:50 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		52.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		52.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
	8254									



ESTHERVILLE SUB	SIMN	69.39	121F2-121.F2 - Loose joint bars	Repaired Before Traffic	06/29/2016	Installed bolt or bolts	06/29/2016	installed 2 bolts
-----------------	------	-------	---------------------------------	-------------------------	------------	-------------------------	------------	-------------------

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/01/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Lee Cameron
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/01/2016 02:16:29 PM**Date Inspection Closed by Inspector:** 07/01/2016 02:05:25 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

Roelyn Ind Lead, Inspected By J C Davis, Fort Dodge Track Inspector

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/05/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/05/2016 03:02:32 PM**Date Inspection Closed by Inspector:** 07/05/2016 03:02:32 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
		8253							

TWIN CITIES	ESTHERVILLE SUB	SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	16.16		37B1-37.B1 - Vegetation obstru	Scheduled for Repair	07/05/2016	Corr from Trk Mtce Plan	07/07/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 07/07/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/07/2016 02:35:30 PM

**Date Inspection Closed by Inspector:** 07/07/2016 02:35:30 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------------	----	--------------------	------------------	-----------------	----------------------	-------------------	-----------------------	---------	----------

ESTHERVILLE SUB	8253 SIMN	32.82		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/07/2016	Corr from Trk Mtce Plan	07/18/2016		4 ties
ESTHERVILLE SUB	8253 SIMN	32.80		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/07/2016	Corr from Trk Mtce Plan	07/18/2016		5 ties
ESTHERVILLE SUB	8253 SIMN	32.81		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/07/2016	Corr from Trk Mtce Plan	07/18/2016		7 ties

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 07/12/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Jay Weber
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 07/12/2016 02:59:13 PM

**Date Inspection Closed by Inspector:** 07/12/2016 02:59:13 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
track inspection with Jason Waldsmchmidt									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 07/15/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> HI-Rail

Date Inspection Uploaded into the Central System: 07/15/2016 04:12:07 PM  
 Date Inspection Closed by Inspector: 07/15/2016 04:02:37 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	73.12		109B2-109.B2 - Crossties not ef	Scheduled for Repair	07/15/2016	Corr from Trk Mtce Plan	07/29/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 07/16/2016 Inspected By: Jay Weber  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: HI-Rail

Date Inspection Uploaded into the Central System: 07/16/2016 02:42:00 PM  
 Date Inspection Closed by Inspector: 07/16/2016 02:35:40 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 07/19/2016    **Inspected By:** Jay Weber  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail

**Date Inspection Uploaded into the Central System:** 07/19/2016 07:20:05 PM

**Date Inspection Closed by Inspector:** 07/19/2016 07:13:30 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 07/20/2016    **Inspected By:** Jay Weber  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail

**Date Inspection Uploaded into the Central System:** 07/20/2016 08:49:40 PM

**Date Inspection Closed by Inspector:** 07/20/2016 08:44:54 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
		8268	-						

TWIN CITIES	ESTHERVILLE SUB	SIMN		70.56	78.46	Yes	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	Yes	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 07/23/2016      **Inspected By:** Jay Weber  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Clear      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 07/23/2016 03:50:23 PM

**Date Inspection Closed by Inspector:** 07/23/2016 03:39:06 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
		8253	02						

TWIN CITIES	ESTHERVILLE SUB	SIDE	103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 07/26/2016    **Inspected By:** Jay Weber  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail

**Date Inspection Uploaded into the Central System:** 07/26/2016 05:40:08 PM

**Date Inspection Closed by Inspector:** 07/26/2016 05:27:56 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Ring Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	35.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	35.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

--	--	--	--	--	--	--	--	--	--

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	34.80	Deviation : <b>1.125</b>	103B-103.B - Fouled or insuffi	Scheduled for Repair	07/26/2016	Corr from Trk Mtce Plan	08/24/2016		
ESTHERVILLE SUB	8253 SIMN -	19.90	Deviation Zero : <b>1.5</b>	63A3-63.A3 - Deviation from ze	Repaired Before Traffic	07/26/2016	Tamped to Surface Track	07/26/2016		
ESTHERVILLE SUB	8253 SIMN -	31.65	Deviation Zero : <b>1.5</b>	63A3-63.A3 - Deviation from ze	Repaired Before Traffic	07/26/2016	Tamped to Surface Track	07/26/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 07/29/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 07/29/2016 05:39:47 PM

**Date Inspection Closed by Inspector:** 07/29/2016 05:29:22 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	25.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR



TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	25.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	73.13	Number of Ties : 10	109BA-109.B1i - 39-foot segment	Scheduled for Repair	07/29/2016	Corr from Trk Mtce Plan	08/05/2016		
ESTHERVILLE SUB	8254 SIMN -	58.50		127A3-127.A3 - Insufficient fas	Scheduled for Repair	07/29/2016	Corr from Trk Mtce Plan	08/25/2016		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 07/30/2016    **Inspected By:** Jay Weber  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail

**Date Inspection Uploaded into the Central System:** 07/30/2016 02:42:54 PM

**Date Inspection Closed by Inspector:** 07/30/2016 02:32:36 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	34.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	34.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	9.20		135H1-135.H1 - Unusually chippe	Remove From Service	07/30/2016	Corr from Trk Mtce Plan	08/02/2016		
ESTHERVILLE SUB	8253 SIMN -	19.90	Deviation Zero : 1.25	63A3-63.A3 - Deviation from ze	Slow Order to 25 mph	07/30/2016				

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/02/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/02/2016 03:26:26 PM

**Date Inspection Closed by Inspector:** 08/02/2016 03:20:48 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	45.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	45.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	41.50	Number of Bolts : 2	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/02/2016	Installed bolt or bolts	08/02/2016		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ ZTS	ZTS		Segment/ ZTS	ZTS		

		Track			Track			
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	45.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	REISWIG	DEURLOO	GOLD EAGLE COOP

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 08/05/2016 Inspected By: Jay Weber  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 08/05/2016 04:57:21 PM

Date Inspection Closed by Inspector: 08/05/2016 04:51:41 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 768	78.41	78.47	No	?	?	NORTH TAIL
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
-------------	-----------------	-----------	---	-------	-------	----	---------	---------	---------------------------

TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
USED DUSTIN DICKYS TRACK WARRANT52-47									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	73.12	Number of Ties : 10	109BA-109.B1i - 39-foot segment	Scheduled for Repair	08/05/2016	Corr from Trk Mtce Plan	09/02/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	50.00	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 768	78.41	78.47	?	?	NORTH TAIL

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 08/06/2016 Inspected By: Jay Weber  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 08/06/2016 03:57:48 PM

Date Inspection Closed by Inspector: 08/06/2016 03:48:39 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	50.00	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	45.60		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN	45.60		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN	45.60		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN	45.60		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN	45.60		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN -	8.40		135D-135.D - Heel of switch in	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN -	8.40		135D-135.D - Heel of switch in	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	08/19/2016		
ESTHERVILLE SUB	8253 SIMN -	8.40		135D-135.D - Heel of switch in	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN -	8.40		135D-135.D - Heel of switch in	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		
ESTHERVILLE SUB	8253 SIMN -	8.40		135D-135.D - Heel of switch in	Scheduled for Repair	08/06/2016	Corr from Trk Mtce Plan	09/02/2016		

**Switches Inspected**

Switch	From Track		To Track		User

Inspected by	Subdivision	Segment/ Track	ZTS	Mile Value	Segment/ Track	ZTS	Switch Description	Frog Type Description
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	50.00	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 08/09/2016     **Inspected By:** Jay Weber  
**Inspection Type:** FRA Required     **Relief Inspector:** Data not entered  
**Weather:** Clear     **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/09/2016 04:20:57 PM  
**Date Inspection Closed by Inspector:** 08/09/2016 03:12:04 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC



TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	44.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	44.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.43		135D-135.D - Heel of switch in	Repaired Before Traffic	08/09/2016	Repaired	08/09/2016		
ESTHERVILLE SUB	8253 SIMN	32.43		135D-135.D - Heel of switch in	Repaired Before Traffic	08/09/2016	Repaired	08/09/2016		
ESTHERVILLE SUB	8253 SIMN	32.43		135D-135.D - Heel of switch in	Repaired Before Traffic	08/09/2016	Repaired	08/09/2016		
ESTHERVILLE SUB	8253 SIMN	32.43		135D-135.D - Heel of switch in	Repaired Before Traffic	08/09/2016	Repaired	08/09/2016		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point



Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/10/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 08/10/2016 03:37:01 PM

Date Inspection Closed by Inspector: 08/10/2016 03:32:35 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		44.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 768	78.41	78.47	No	?	?	NORTH TAIL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		44.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments****Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/12/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/12/2016 05:13:40 PM

**Date Inspection Closed by Inspector:** 08/12/2016 05:11:46 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	44.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	44.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
Flash Floods									

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/16/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/16/2016 09:59:53 PM

**Date Inspection Closed by Inspector:** 08/16/2016 09:55:35 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP

TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	Yes	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	Yes	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/17/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/17/2016 07:50:47 PM

**Date Inspection Closed by Inspector:** 08/17/2016 07:42:12 PM

**Tracks Inspected**

		<b>Seg/</b>	<b>Zone/</b>	<b>Begin</b>	<b>End</b>	<b>Rail</b>	
--	--	-------------	--------------	--------------	------------	-------------	--

Service Unit	Subdivision	Trk Type	Track	MP	MP	Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		35.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 768	78.41	78.47	No	?	?	NORTH TAIL
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		35.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN -	27.10		121D1-121.D1 - Less than 2 bolt	Repaired Before Traffic	08/17/2016	Repaired	08/17/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/19/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/19/2016 11:27:27 PM

**Date Inspection Closed by Inspector:** 08/19/2016 11:20:55 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	8.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	8.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
Flash Floods Display/Slow Boards									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/20/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/20/2016 07:25:12 PM

**Date Inspection Closed by Inspector:** 08/20/2016 07:21:28 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	10.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	10.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/24/2016	<b>Inspected By:</b> Gary Brockman
------------------------------------	------------------------------------

Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 08/24/2016 03:35:31 PM

Date Inspection Closed by Inspector: 08/24/2016 03:25:45 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									
Special Inspection, Flash Flood Estherville Sub MP 24 to MP 48.0 And Tara Sub MP 70.10 to Mp 60 , No defects Noted									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	77.90	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	08/24/2016	Installed bolt or bolts	08/24/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 YARD 02 729	48.64 48.62		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	08/24/2016	Removed obstruction	08/24/2016		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/27/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/27/2016 04:40:29 PM

**Date Inspection Closed by Inspector:** 08/27/2016 04:35:39 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	44.36		109B2-109.B2 - Crossties not ef	Scheduled for Repair	08/27/2016	Corr from Trk Mtce Plan	09/07/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 08/29/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> Special	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 08/30/2016 07:22:52 AM

**Date Inspection Closed by Inspector:** 08/29/2016 08:11:31 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	21.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	21.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	--------------	---	------	-------	----	---------	---------	-------------------------

#### Comments

Flash Flood

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 08/31/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 08/31/2016 06:07:50 PM

**Date Inspection Closed by Inspector:** 08/31/2016 06:00:59 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	63.65		109B2-109.B2 - Crossties not ef	Scheduled for Repair	08/31/2016	Corr from Trk Mtce Plan	09/09/2016		
ESTHERVILLE SUB	8254 SIMN -	63.65		109B2-109.B2 - Crossties not ef	Scheduled for Repair	08/31/2016	Corr from Trk Mtce Plan	09/09/2016		
ESTHERVILLE SUB	8254 SIMN -	63.74		109B2-109.B2 - Crossties not ef	Scheduled for Repair	08/31/2016	Corr from Trk Mtce Plan	09/09/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found



## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 09/03/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 09/03/2016 03:52:25 PM

**Date Inspection Closed by Inspector:** 09/03/2016 03:46:48 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	38.09		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/03/2016	Corr from Trk Mtce Plan	09/28/2016		
ESTHERVILLE SUB	8253 SIMN	39.85		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/03/2016	Corr from Trk Mtce Plan	09/06/2016		

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 09/07/2016    **Inspected By:** Kyle Olson  
**Inspection Type:** FRA Required    **Relief Inspector:** Kyle Olson  
**Weather:** Data not entered    **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 09/07/2016 02:35:20 PM

Date Inspection Closed by Inspector: 09/07/2016 02:35:20 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
eshterville sub									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 09/08/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/08/2016 03:52:49 PM

Date Inspection Closed by Inspector: 09/08/2016 03:45:34 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02/767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02/002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02/767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	70.28		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/08/2016	Corr from Trk Mtce Plan	10/05/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/10/2016	Inspected By: Gary Brockman
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/10/2016 04:58:25 PM

Date Inspection Closed by Inspector: 09/10/2016 04:53:22 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	76.90		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/10/2016	Corr from Trk Mtce Plan	10/05/2016		
ESTHERVILLE SUB	8268 SIMN -	77.13		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/10/2016	Corr from Trk Mtce Plan	10/05/2016		

### Switches Inspected

Switch	Subdivision	From Track		To Track		User	Frog Type Description
		Mile Value			Mile Value		

Inspected by		Segment/ Track	ZTS		Segment/ Track	ZTS	Switch Description	
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.20 32.19		133A9-133.A9 - Loose or missing	Repaired Before Traffic	09/10/2016	Tightened adjustable rail braces	09/10/2016		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/15/2016 Inspected By: Gary Brockman  
Inspection Type: FRA Required Relief Inspector: Data not entered  
Weather: Clear How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 09/15/2016 03:53:13 PM

Date Inspection Closed by Inspector: 09/15/2016 03:48:18 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.33		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/15/2016	Corr from Trk Mtce Plan	10/10/2016		
ESTHERVILLE SUB	8253 SIMN	39.74		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/15/2016	Corr from Trk Mtce Plan	10/10/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	09/15/2016	Tightened adjustable rail braces	09/15/2016		
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	09/15/2016	Tightened adjustable rail braces	09/15/2016		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/16/2016 Inspected By: Gary Brockman  
 Inspection Type: FRA Required Relief Inspector: Data not entered  
 Weather: Clear How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 09/16/2016 03:30:47 PM

Date Inspection Closed by Inspector: 09/16/2016 03:22:09 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETTSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02-103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Special Inspections Flash Flooding, Estherville Sub MP 0.0 To MP 78.4, Laurens Sub MP 0.0 To MP 28.5 And Tara Sub MP 0.0 To MP 70.10 , Inspection Started At 2100 Hrs 09-15-16									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 09/17/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 09/17/2016 03:34:05 PM

**Date Inspection Closed by Inspector:** 09/17/2016 03:27:13 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	Yes	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	69.61	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	09/17/2016	Installed bolt or bolts	09/17/2016		
ESTHERVILLE SUB	8254 SIMN -	48.59		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	09/17/2016	Tightened frog bolt	09/17/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 09/20/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 09/20/2016 03:35:48 PM**Date Inspection Closed by Inspector:** 09/20/2016 03:31:18 PM**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	77.63		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/20/2016	Corr from Trk Mtce Plan	10/07/2016		
ESTHERVILLE SUB	8268 SIMN -	77.70		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/20/2016	Corr from Trk Mtce Plan	10/07/2016		
ESTHERVILLE SUB	8268 SIMN -	77.71		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/20/2016	Corr from Trk Mtce Plan	10/07/2016		
ESTHERVILLE SUB	8268 SIMN -	71.50		37C3-37.C3 - Excessive vegetat	Repaired Before Traffic	09/20/2016	Removed vegetation from walk way and toepath	09/20/2016		
ESTHERVILLE SUB	8268 SIMN -	77.30		37C3-37.C3 - Excessive vegetat	Repaired Before Traffic	09/20/2016	Removed vegetation from walk way and toepath	09/20/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 09/21/2016    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Clear    **How Conducted:** Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/21/2016 04:00:49 PM

Date Inspection Closed by Inspector: 09/21/2016 03:55:03 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									
Special Inspection , Heat MP 0 to MP 32.25 . 91 Degrees at 14:45 pm									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 09/23/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/23/2016 04:38:52 PM

Date Inspection Closed by Inspector: 09/23/2016 04:35:54 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									



### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	62.56		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/19/2016		
ESTHERVILLE SUB	8254 SIMN -	62.58		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/19/2016		
ESTHERVILLE SUB	8254 SIMN -	70.36		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/19/2016		
ESTHERVILLE SUB	8254 SIMN -	70.41		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/19/2016		
ESTHERVILLE SUB	8254 SIMN -	70.55		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/12/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN -	70.56 70.55		127A-127.A - Failure of fasten	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/12/2016		
ESTHERVILLE SUB	8268 SIMN -	71.17 71.17		135.E1 -135.E1 - Switch stand or	Scheduled for Repair	09/23/2016	Corr from Trk Mtce Plan	10/12/2016		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/27/2016    Inspected By: Gary Brockman  
 Inspection Type: FRA Required    Relief Inspector: Data not entered  
 Weather: Clear    How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/27/2016 05:13:58 PM

Date Inspection Closed by Inspector: 09/27/2016 05:03:05 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/	Zone/	Begin	End	Rail Xing	Director	Manager	Track Description
--------------	-------------	------	-------	-------	-----	-----------	----------	---------	-------------------

		Trk Type	Track	MP	MP	Insp			
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	63.50	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	63.50	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	67.32		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/27/2016	Corr from Trk Mtce Plan	10/21/2016		
ESTHERVILLE SUB	8254 SIMN -	68.46		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/27/2016	Corr from Trk Mtce Plan	10/21/2016		
ESTHERVILLE SUB	8254 SIMN -	69.73		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/27/2016	Corr from Trk Mtce Plan	10/21/2016		
ESTHERVILLE SUB	8254 SIMN -	69.77		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/27/2016	Corr from Trk Mtce Plan	10/21/2016		
ESTHERVILLE SUB	8254 SIMN -	70.02		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/27/2016	Corr from Trk Mtce Plan	10/21/2016		
ESTHERVILLE SUB	8254 SIMN -	70.02		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/27/2016	Corr from Trk Mtce Plan	10/21/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 09/28/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 09/28/2016 04:11:45 PM

**Date Inspection Closed by Inspector:** 09/28/2016 04:08:08 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02_767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02_767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
		8254	ZZ						

TWIN CITIES	ESTHERVILLE SUB	CROS	269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	59.70		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/28/2016	Corr from Trk Mtce Plan	10/25/2016		
ESTHERVILLE SUB	8254 SIMN -	59.71		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/28/2016	Corr from Trk Mtce Plan	10/25/2016		
ESTHERVILLE SUB	8254 SIMN -	70.43		109B2-109.B2 - Crossties not ef	Scheduled for Repair	09/28/2016	Corr from Trk Mtce Plan	10/12/2016		
ESTHERVILLE SUB	8254 SIMN -	59.70	Number of Bolts : 2	121E-121.E - Less than 2 bolts	Repaired Before Traffic	09/28/2016	Installed bolt or bolts	09/28/2016		
ESTHERVILLE SUB	8254 SIMN -	59.70	Number of Bolts : 2	121E-121.E - Less than 2 bolts	Repaired Before Traffic	09/28/2016	Installed bolt or bolts	09/28/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/01/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 10/01/2016 04:45:52 PM

**Date Inspection Closed by Inspector:** 10/01/2016 04:36:11 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN	-	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	50.29		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/01/2016	Corr from Trk Mtce Plan	10/10/2016		
ESTHERVILLE SUB	8268 SIMN -	74.44	Number of Non- Defective Crossties : 5	109B4-109.B4 - Failure to maint	Slow Order to 10 mph	10/01/2016	Corr from Trk Mtce Plan	10/18/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/04/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Clear	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/04/2016 04:20:29 PM

**Date Inspection Closed by Inspector:** 10/04/2016 04:14:53 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	58.50	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN	-	0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN	-	48.49	58.50	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN -	57.55		109B2-109.B2 - Crossties not ef	213.9B	10/04/2016	Corr from Trk Mtce Plan	10/10/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 10/05/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/05/2016 04:42:54 PM

**Date Inspection Closed by Inspector:** 10/05/2016 04:42:54 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		53.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		53.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Estherville Sub MP 60 to MP 53 Inspected under UP Weber Warrant # 36-29									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	76.72		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/05/2016	Corr from Trk Mtce Plan	10/07/2016		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 10/08/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/08/2016 04:34:46 PM

**Date Inspection Closed by Inspector:** 10/08/2016 04:34:47 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.43	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	10/08/2016	Corr from Trk Mtce Plan	10/08/2016	GARY BROCKMAN	

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 10/11/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 10/11/2016 03:59:07 PM

Date Inspection Closed by Inspector: 10/11/2016 03:59:07 PM

## Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL

## Comments

## Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	8.43		135D-135.D - Heel of switch in	Repaired Before Traffic	10/11/2016	Corr from Trk Mtce Plan	10/11/2016	GARY BROCKMAN	

## Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.19 32.18		135D-135.D - Heel of switch in	Scheduled for Repair	10/11/2016	Corr from Trk Mtce Plan	10/17/2016		
ESTHERVILLE SUB	8253 SIMN	32.43 0.00		137E-137.E - Severe frog condi	Scheduled for Repair	10/11/2016	Corr from Trk Mtce Plan	11/07/2016		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 10/12/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/12/2016 04:38:23 PM

**Date Inspection Closed by Inspector:** 10/12/2016 04:38:23 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Ring Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETTSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETTSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone /	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------	----	--------------------	------------------	-----------------	----------------------	-------------------	-----------------------	---------	----------



Track									
ESTHERVILLE SUB	<u>8254</u> SIMN	67.58		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/12/2016	Corr from Trk Mtce Plan	10/21/2016	
ESTHERVILLE SUB	<u>8268</u> SIMN	75.40		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/12/2016	Corr from Trk Mtce Plan	10/18/2016	
ESTHERVILLE SUB	<u>8268</u> SIMN	77.85		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/12/2016	Corr from Trk Mtce Plan	10/18/2016	
ESTHERVILLE SUB	<u>8268</u> SIMN	77.90		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/12/2016	Corr from Trk Mtce Plan	10/18/2016	
ESTHERVILLE SUB	<u>8268</u> SIMN	77.21	Distance to nearest effective tie : <b>20</b>	109B3-109.B3 - No effective sup	213.9B	10/12/2016	Corr from Trk Mtce Plan	10/18/2016	

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	<u>8268</u> SIMN	-	77.77	<u>8268</u> INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	<u>8268</u> SIMN	-	78.45	<u>8268</u> INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/15/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/15/2016 03:59:12 PM

**Date Inspection Closed by Inspector:** 10/15/2016 03:59:12 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	59.50	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> CROS	<u>77</u> 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	59.50	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Comments**

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	49.57		109B2-109.B2 - Crossties not ef	Scheduled for Repair	10/15/2016	Corr from Trk Mtce Plan	10/25/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/18/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/18/2016 04:28:12 PM

**Date Inspection Closed by Inspector:** 10/18/2016 04:28:12 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02_103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Comments

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 10/19/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/19/2016 03:38:55 PM

**Date Inspection Closed by Inspector:** 10/19/2016 03:38:55 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	69.93		109B2-109.B2 - Crossties not ef	Repaired Before Traffic	10/19/2016	Corr from Trk Mtce Plan	10/19/2016	GARY BROCKMAN	

#### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 10/22/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/22/2016 05:09:50 PM

**Date Inspection Closed by Inspector:** 10/22/2016 05:09:50 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	48.59		127A-127.A - Failure of fasten	Scheduled for Repair	10/22/2016	Corr from Trk Mtce Plan	10/25/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/25/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/25/2016 04:08:49 PM

**Date Inspection Closed by Inspector:** 10/25/2016 04:08:49 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Comments

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 10/26/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Dustin Dickey
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 10/26/2016 02:51:39 PM

**Date Inspection Closed by Inspector:** 10/26/2016 02:51:39 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		63.00	64.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		63.00	64.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
-------------	-----------------	--------------	--	-------	-------	----	---------	---------	---------------------------

#### Comments

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	63.59		109B2-109.B2 - Crossties	Scheduled for	10/26/2016	Corr from Trk	10/28/2016		15 ties

				not ef	Repair		Mtce Plan			
ESTHERVILLE SUB	<u>8254</u> <u>SIMN</u>	63.70		109B2-109.B2 - Crossties not ef	Slow Order to 25 mph	10/26/2016	Corr from Trk Mtce Plan	10/28/2016		15 ties

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 10/29/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 10/29/2016 04:50:01 PM

**Date Inspection Closed by Inspector:** 10/29/2016 04:50:02 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> <u>SIMN</u>		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> <u>SIMN</u>		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> <u>SIDE</u>	<u>02</u> <u>103</u>	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> <u>SIDE</u>	<u>02</u> <u>103</u>	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> <u>SIMN</u>		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> <u>SIMN</u>		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

--

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	16.45		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	10/29/2016	Corr from Trk Mtce Plan	10/29/2016	GARY BROCKMAN	
ESTHERVILLE SUB	<u>8254</u> <u>SIMN</u>	50.00		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	10/29/2016	Corr from Trk Mtce Plan	10/29/2016	GARY BROCKMAN	
ESTHERVILLE SUB	<u>8254</u> <u>SIMN</u>	48.49		37C3-37.C3 - Excessive vegetat	Repaired Before Traffic	10/29/2016	Corr from Trk Mtce Plan	10/29/2016	GARY BROCKMAN	
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	15.50		37.E3 -37.E3 - Vegetation brushl	Repaired Before Traffic	10/29/2016	Corr from Trk Mtce Plan	10/29/2016	GARY BROCKMAN	

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/01/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/01/2016 05:38:01 PM  
**Date Inspection Closed by Inspector:** 11/01/2016 05:38:01 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		60.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		60.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	74.00		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	11/01/2016	Corr from Trk Mtce Plan	11/01/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8268 SIMN	75.00		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	11/01/2016	Corr from Trk Mtce Plan	11/01/2016	GARY BROCKMAN	

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/02/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/02/2016 06:45:33 PM  
**Date Inspection Closed by Inspector:** 11/02/2016 06:45:33 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	66.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	66.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Comments									
MP 0.0 to MP 33.0 , Inspected by Kyle Olsen Section Foreman									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	66.00		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	11/02/2016	Corr from Trk Mtce Plan	11/02/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8254 SIMN	63.60		37C1-37.C1 - Vegetation interf	Repaired Before Traffic	11/02/2016	Corr from Trk Mtce Plan	11/02/2016	GARY BROCKMAN	

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/04/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/04/2016 07:14:17 PM

**Date Inspection Closed by Inspector:** 11/04/2016 07:14:17 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	58.50	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	58.50	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
	8254									



ESTHERVILLE SUB	<u>SIMN</u>	58.44		109B2-109.B2 - Crossties not ef	Scheduled for Repair	11/04/2016	Corr from Trk Mtce Plan	11/09/2016		
ESTHERVILLE SUB	<u>8254 SIMN</u>	58.34		127A-127.A - Failure of fasten	Scheduled for Repair	11/04/2016	Corr from Trk Mtce Plan	11/10/2016		
ESTHERVILLE SUB	<u>8254 SIMN</u>	58.35		127A-127.A - Failure of fasten	Scheduled for Repair	11/04/2016	Corr from Trk Mtce Plan	11/10/2016		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 11/05/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/05/2016 05:53:16 PM

**Date Inspection Closed by Inspector:** 11/05/2016 05:53:16 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253 SIMN</u>	33.25		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	11/05/2016	Corr from Trk Mtce Plan	11/05/2016	GARY BROCKMAN	
ESTHERVILLE SUB	<u>8253 SIMN</u>	39.20		37C1-37.C1 - Vegetation interf	Repaired Before Traffic	11/05/2016	Corr from Trk Mtce Plan	11/05/2016	GARY BROCKMAN	
ESTHERVILLE SUB	<u>8253 SIMN</u>	41.60		37C1-37.C1 - Vegetation interf	Repaired Before Traffic	11/05/2016	Corr from Trk Mtce Plan	11/05/2016	GARY BROCKMAN	

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/08/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/08/2016 04:11:11 PM

**Date Inspection Closed by Inspector:** 11/08/2016 04:11:11 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									
Tara Sub OUT OF SEVICE, Between MP 58.25 to MP 70.10									

#### Track Defects

No track defect records found

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/10/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/10/2016 06:07:49 PM

**Date Inspection Closed by Inspector:** 11/10/2016 06:07:50 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

		SIMN							
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									
Track defect MP 46.40, Center Broke Joint Bar. Protected Trk Warrant # 3820									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	46.40		119C-119.C - Failure to comply	Scheduled for Repair	11/10/2016	Corr from Trk Mtce Plan	12/05/2016		
ESTHERVILLE SUB	8253 SIMN	46.40		121C2-121.C2 - Center cracked o	213.9B	11/10/2016	Corr from Trk Mtce Plan	11/14/2016		Defect Protected Trk Warrant # 38-20 GOB

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.19 32.18		133A9-133.A9 - Loose or missing	Repaired Before Traffic	11/10/2016	Corr from Trk Mtce Plan	11/10/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8253 SIDE 02 103	31.03 31.01		127A-127.A - Failure of fasten	Scheduled for Repair	11/10/2016	Corr from Trk Mtce Plan	11/29/2016		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/12/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/12/2016 02:48:05 PM

**Date Inspection Closed by Inspector:** 11/12/2016 02:48:05 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.57 33.22		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	11/12/2016	Corr from Trk Mtce Plan	11/12/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8253 SIMN	48.49 48.49		133A9-133.A9 - Loose or missing	Repaired Before Traffic	11/12/2016	Corr from Trk Mtce Plan	11/12/2016	GARY BROCKMAN	

### Joint Bar Inspections

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/14/2016      **Inspected By:** Kyle Olson  
**Inspection Type:** FRA Required      **Relief Inspector:** Kyle Olson  
**Weather:** Data not entered      **How Conducted:** Data not entered

**Date Inspection Uploaded into the Central System:** 11/14/2016 02:42:39 PM

**Date Inspection Closed by Inspector:** 11/14/2016 02:42:39 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	45.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	45.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

#### Comments

estherville

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	41.50	Number of Bolts : 2	121E-121.E - Less than 2 bolts	F-K	11/14/2016	Repaired	11/14/2016		pull apart, drifted together and replaced 2 bolts

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 11/19/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/19/2016 04:04:42 PM

**Date Inspection Closed by Inspector:** 11/19/2016 04:04:43 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254	ZZ	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)

		CROS	269						
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

--	--	--	--	--	--	--	--	--	--

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Eleavtor	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	70.57 70.56		133A9-133.A9 - Loose or missing	Repaired Before Traffic	11/19/2016	Corr from Trk Mtce Plan	11/19/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8268 SIMN	70.57 70.56		133A9-133.A9 - Loose or missing	Repaired Before Traffic	11/19/2016	Corr from Trk Mtce Plan	11/19/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8268 SIMN	77.77 77.75		133AD-133.A13 - Loose, worn, or	Repaired Before Traffic	11/19/2016	Corr from Trk Mtce Plan	11/19/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8268 SIMN	78.45 78.43		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	11/19/2016	Corr from Trk Mtce Plan	11/19/2016	GARY BROCKMAN	

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/21/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/21/2016 03:00:45 PM  
**Date Inspection Closed by Inspector:** 11/21/2016 03:00:45 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.20	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/23/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/23/2016 11:16:22 AM  
**Date Inspection Closed by Inspector:** 11/23/2016 11:16:22 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
		8253							

TWIN CITIES	ESTHERVILLE SUB	SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.75	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.75	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Comments									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	31.03		135D-135.D - Heel of switch in	Repaired Before Traffic	11/23/2016	Corr from Trk Mtce Plan	11/23/2016	DUSTIN DICKEY	

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.20	33.75	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 11/27/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Jay Weber
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Data not entered

**Date Inspection Uploaded into the Central System:** 11/27/2016 02:01:01 PM

**Date Inspection Closed by Inspector:** 11/27/2016 02:01:02 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**

No track defect records found



**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 11/30/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 11/30/2016 04:24:06 PM

**Date Inspection Closed by Inspector:** 11/30/2016 04:24:06 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments****Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 12/01/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/01/2016 03:47:27 PM

**Date Inspection Closed by Inspector:** 12/01/2016 03:47:27 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/03/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/03/2016 05:03:25 PM

**Date Inspection Closed by Inspector:** 12/03/2016 05:03:26 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	16.15		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	12/03/2016	Corr from Trk Mtce Plan	12/03/2016	GARY BROCKMAN	Brush cutter Removed Brush
ESTHERVILLE SUB	8253 SIMN	16.30		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	12/03/2016	Corr from Trk Mtce Plan	12/03/2016	GARY BROCKMAN	Brushcutter removed Brush

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

## No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/04/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/04/2016 04:29:51 PM

**Date Inspection Closed by Inspector:** 12/04/2016 04:29:51 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	27.25	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	27.25	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	21.59		103A-103.A - Fouled or insuffi	Scheduled for Repair	12/04/2016	Corr from Trk Mtce Plan	12/07/2016		
ESTHERVILLE SUB	8253 SIMN	21.59		33A3-33.A3 - Drainage or water	Scheduled for Repair	12/04/2016	Corr from Trk Mtce Plan	12/07/2016		

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/07/2016      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/07/2016 04:37:26 PM

**Date Inspection Closed by Inspector:** 12/07/2016 04:37:26 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253	02	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

		SIDE	103					
<b>Comments</b>								

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	22.25		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	12/07/2016	Corr from Trk Mtce Plan	12/07/2016	GARY BROCKMAN	
ESTHERVILLE SUB	8253 SIMN	27.25		37B1-37.B1 - Vegetation obstru	Repaired Before Traffic	12/07/2016	Corr from Trk Mtce Plan	12/07/2016	GARY BROCKMAN	

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/08/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/08/2016 03:55:28 PM

**Date Inspection Closed by Inspector:** 12/08/2016 03:55:28 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02_117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02_767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02_767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02_730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02_729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02_732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77_269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02_733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02_117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

--	--	--	--	--	--	--	--	--	--

### Track Defects

Subdivision	Seg / Trk Type / Zone /	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action	Permanent Repairs	Permanent Repair	By Whom	Comments
-------------	-------------------------	----	--------------------	------------------	-----------------	-----------------	-------------------	------------------	---------	----------

	Track					Date		Date		
ESTHERVILLE SUB	8254 CNRT 02 117	48.53		127A-127.A - Failure of fasten	Scheduled for Repair	12/08/2016	Corr from Trk Mtce Plan	12/09/2016		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	71.21 71.21		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	12/08/2016	Corr from Trk Mtce Plan	12/08/2016	GARY BROCKMAN	removed Debris from Point
ESTHERVILLE SUB	8268 SIMN	77.77 77.75		133AD-133.A13 - Loose, worn, or	Repaired Before Traffic	12/08/2016	Corr from Trk Mtce Plan	12/08/2016	GARY BROCKMAN	

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 12/09/2016 Inspected By: Dustin Dickey  
Inspection Type: FRA Required Relief Inspector: Brockman, Gary  
Weather: Data not entered How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 12/09/2016 02:07:17 PM

Date Inspection Closed by Inspector: 12/09/2016 02:07:17 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/	Zone/	Begin	End	Rail Xing	Director	Manager	Track Description
--------------	-------------	------	-------	-------	-----	-----------	----------	---------	-------------------

		Trk Type	Track	MP	MP	Insp			
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/10/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 12/10/2016 12:41:01 PM

Date Inspection Closed by Inspector: 12/10/2016 12:41:01 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/12/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/12/2016 03:26:59 PM  
**Date Inspection Closed by Inspector:** 12/12/2016 03:26:59 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	33.13		121F2-121.F2 - Loose joint bars	Repaired Before Traffic	12/12/2016	Corr from Trk Mtce Plan	12/12/2016	DUSTIN DICKEY	

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
 FRA Track Inspection & Defect Report**

**Inspection Date:** 12/13/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/13/2016 02:48:10 PM  
**Date Inspection Closed by Inspector:** 12/13/2016 02:48:10 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

report 109

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/14/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/14/2016 03:50:31 PM

**Date Inspection Closed by Inspector:** 12/14/2016 03:50:31 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments**

All defects noted on DOT report

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 12/15/2016      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/15/2016 12:55:24 PM

**Date Inspection Closed by Inspector:** 12/15/2016 12:55:25 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/	Zone/	Begin	End	Rail Xing	Director	Manager	Track Description
--------------	-------------	------	-------	-------	-----	--------------	----------	---------	-------------------



		Trk Type	Track	MP	MP	Insp			
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/19/2016	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Brockman, Gary
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/19/2016 02:42:32 PM

**Date Inspection Closed by Inspector:** 12/19/2016 02:42:32 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
snow cover									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	58.50		135D-135.D - Heel of switch in	Repaired Before Traffic	12/19/2016	Corr from Trk Mtce Plan	12/19/2016	DUSTIN DICKEY	

**Switch Defects**  
No switch defect records found

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/21/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/21/2016 03:21:35 PM

**Date Inspection Closed by Inspector:** 12/21/2016 03:21:35 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP

#### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments**

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 INDU 02 809	47.22		205C2-205.C2 - Insecure derail	Scheduled for Repair	12/21/2016	Corr from Trk Mtce Plan	01/03/2017		

#### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length

#### Switch Defects

Seg /									
-------	--	--	--	--	--	--	--	--	--

Subdivision	Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>9.19</u> 9.16		133A9-133.A9 - Loose or missing	Repaired Before Traffic	12/21/2016	Corr from Trk Mtce Plan	12/21/2016		
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>33.57</u> 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	12/21/2016	Corr from Trk Mtce Plan	12/21/2016		

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 12/23/2016	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/23/2016 03:37:38 PM

**Date Inspection Closed by Inspector:** 12/23/2016 03:37:38 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Estherville Sub MP 48.49 to MP 78.46, Inspected By Kyle Olsen Section Foreman									

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	<u>8253</u> SIMN	-	31.03	<u>8253</u> SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.19	<u>8253</u> SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.2	<u>8253</u> YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.27	<u>8253</u> INDU	02 -723	West Bend Processing	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>46.11</u> 46.11		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	12/23/2016	Corr from Trk Mtce Plan	12/23/2016		Ice And Snow Removed

ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	<u>47.16</u> 47.16		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	12/23/2016	Corr from Trk Mtce Plan	12/23/2016		
-----------------	----------------------------	-----------------------	--	------------------------------------	----------------------------	------------	----------------------------	------------	--	--

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/28/2016	<b>Inspected By:</b> Joel Babcock
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/28/2016 02:40:11 PM

**Date Inspection Closed by Inspector:** 12/28/2016 02:40:11 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 711	9.16	9.19	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> YARD	<u>02</u> 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	39.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 723	32.27	32.40	No	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> YARD	<u>02</u> 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	39.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	32.45		119C-119.C - Failure to comply	Scheduled for Repair	12/28/2016	Corr from Trk Mtce Plan	01/09/2017		
ESTHERVILLE SUB	<u>8253</u> <u>INDU</u> <u>02</u> <u>723</u>	32.27		121C1-121.C1 - Center cracked o	Remove From Service	12/28/2016				
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	32.45		121C2-121.C2 - Center cracked o	Repaired Before Traffic	12/28/2016	Corr from Trk Mtce Plan	12/28/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	32.24	Number of Bolts : <b>3</b>	121E-121.E - Less than 2 bolts	Repaired Before Traffic	12/28/2016	Corr from Trk Mtce Plan	12/28/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	33.55		133A8-133.A8 - Loose or missing	Repaired Before Traffic	12/28/2016	Corr from Trk Mtce Plan	12/28/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	32.20		133A9-133.A9 - Loose or missing	Repaired Before Traffic	12/28/2016	Corr from Trk Mtce Plan	12/28/2016		
ESTHERVILLE SUB	<u>8253</u> <u>SIMN</u>	32.44	Gap Witdh : <b>0.125</b>	135B1-135.B1 - Improper fit bet	Scheduled for Repair	12/28/2016	Corr from Trk Mtce Plan	01/09/2017		
	<u>8253</u>									

ESTHERVILLE SUB	<u>8253</u> SIDE 02 103	31.08		205A-205.A - Derail not clearl	Scheduled for Repair	12/28/2016	Corr from Trk Mtce Plan	01/06/2017		
ESTHERVILLE SUB	<u>8253</u> SIDE 02 103	32.19		205A-205.A - Derail not clearl	Scheduled for Repair	12/28/2016	Corr from Trk Mtce Plan	01/06/2017		
ESTHERVILLE SUB	<u>8253</u> YARD 02 724	32.22		205A-205.A - Derail not clearl	Scheduled for Repair	12/28/2016	Corr from Trk Mtce Plan	01/06/2017		
ESTHERVILLE SUB	<u>8253</u> INDU 02 720	27.17	Gage Measurement : <b>58.25</b>	53B1-53.B1 - Gage dimension on	Remove From Service	12/28/2016				

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	8.4	<u>8253</u> INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	9.19	<u>8253</u> INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	27.13	<u>8253</u> INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	27.84	<u>8253</u> INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	31.03	<u>8253</u> SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.19	<u>8253</u> SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.2	<u>8253</u> YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.27	<u>8253</u> INDU	02 -723	West Bend Processing	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	33.57	<u>8253</u> YARD	02 -724	West Bend Elevator	Railbound Manganese

### Switch Defects

No switch defect records found

### Joint Bar Inspections

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	39.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 720	27.13	27.84	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> YARD	<u>02</u> 724	32.20	32.23	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 723	32.27	32.40	REISWIG	DEURLOO	WEST BEND PROCESSING
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> YARD	<u>02</u> 724	33.54	33.57	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 711	8.40	8.43	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> INDU	<u>02</u> 711	9.16	9.19	REISWIG	DEURLOO	GOLD EAGLE COOP

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 12/28/2016 Inspected By: Kyle Olson  
 Inspection Type: FRA Required Relief Inspector: Brockman, Gary  
 Weather: Data not entered How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 12/28/2016 02:21:50 PM

Date Inspection Closed by Inspector: 12/28/2016 02:21:50 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u>		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

		SIMN							
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		39.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		39.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 12/30/2016	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/30/2016 02:49:44 PM

**Date Inspection Closed by Inspector:** 12/30/2016 02:49:44 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
Comments									
Inspected for Gary Brockman									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 12/30/2016      **Inspected By:** Kyle Olson  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 12/30/2016 02:19:24 PM

**Date Inspection Closed by Inspector:** 12/30/2016 02:19:24 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 01/03/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/03/2017 04:08:58 PM

**Date Inspection Closed by Inspector:** 01/03/2017 04:08:58 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	70.57 70.56		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	01/03/2017	Corr from Trk Mtce Plan	01/03/2017		

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 01/06/2017	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Brockman, Gary
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail

Date Inspection Uploaded into the Central System: 01/06/2017 03:25:59 PM

Date Inspection Closed by Inspector: 01/06/2017 03:25:59 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	32.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	--------------	--	------	-------	----	---------	---------	-------------------------

**Comments**

inspect track

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found



## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 01/07/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/07/2017 05:16:20 PM

**Date Inspection Closed by Inspector:** 01/07/2017 05:16:20 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### Comments

Special Inspection/ Cold Weather

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	71.57		121C2-121.C2 - Center cracked o	Repaired Before Traffic	01/07/2017	Corr from Trk Mtce Plan	01/07/2017		Pulled Joint and Changed Bar

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

No switch defect records found

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/10/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 01/10/2017 03:45:31 PM

Date Inspection Closed by Inspector: 01/10/2017 03:45:31 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

Ice Covered Rails

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 01/12/2017      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/12/2017 02:43:35 PM

**Date Inspection Closed by Inspector:** 01/12/2017 02:43:35 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	59.69		121C2-121.C2 - Center cracked o	Repaired Before Traffic	01/12/2017	Corr from Trk Mtce Plan	01/12/2017		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 01/14/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/14/2017 03:12:04 PM

**Date Inspection Closed by Inspector:** 01/14/2017 03:12:04 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

SIMN
<b>Comments</b>

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	48.59		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	01/14/2017	Corr from Trk Mtce Plan	01/14/2017		Tightened Frog bolt

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/17/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/17/2017 04:10:27 PM

**Date Inspection Closed by Inspector:** 01/17/2017 04:10:27 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Comments

--

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/18/2017	<b>Inspected By:</b> Gary Brockman
------------------------------------	------------------------------------

**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Data not entered    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/18/2017 03:57:07 PM  
**Date Inspection Closed by Inspector:** 01/18/2017 03:57:08 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 01/21/2017    **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required    **Relief Inspector:** Data not entered  
**Weather:** Data not entered    **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/21/2017 03:24:56 PM  
**Date Inspection Closed by Inspector:** 01/21/2017 03:24:56 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

## Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	69.69	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	01/21/2017	Corr from Trk Mtce Plan	01/21/2017		

## Switch Defects

No switch defect records found

## Joint Bar Inspections

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/24/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 01/24/2017 03:47:41 PM

Date Inspection Closed by Inspector: 01/24/2017 03:47:41 PM

## Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

## Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

## Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	31.03	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.19	8253 SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.2	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	33.57	8253 YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	46.11	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.16	8253 INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	47.18	8253 INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	9.19 9.16		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	01/24/2017	Corr from Trk Mtce Plan	01/24/2017		Ice/debris
ESTHERVILLE SUB	8253 SIMN	31.03 31.01		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	01/24/2017	Corr from Trk Mtce Plan	01/24/2017		
ESTHERVILLE SUB	8268 SIMN	70.56 70.55		133A9-133.A9 - Loose or missing	Repaired Before Traffic	01/24/2017	Corr from Trk Mtce Plan	01/24/2017		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	REISWIG	DEURLOO	EMMETTSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 01/27/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/27/2017 03:05:33 PM

**Date Inspection Closed by Inspector:** 01/27/2017 03:05:34 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETTSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIDE	<u>02</u> 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**  
No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP / User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>33.57</u> 33.22		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	01/27/2017	Corr from Trk Mtce Plan	01/27/2017		Tightened Jam Nut
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>33.57</u> 33.22		133A9-133.A9 - Loose or missing	Repaired Before Traffic	01/27/2017	Corr from Trk Mtce Plan	01/27/2017		

**Joint Bar Inspections**  
No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 01/30/2017	<b>Inspected By:</b> Jay Weber
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Brockman, Gary
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 01/30/2017 07:03:25 PM

**Date Inspection Closed by Inspector:** 01/30/2017 07:03:25 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		30.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		30.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
inspect track									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
-------------	-------------------------------	----	--------------------	------------------	-----------------	----------------------	-------------------	-----------------------	---------	----------



ESTHERVILLE SUB	8253 SIMN	41.50	Defect Length : 0.5	113BD-113.B13 - Bolt-hole crack	Repaired Before Traffic	01/30/2017	Corr from Trk Mtce Plan	01/30/2017	JAY WEBER	repaired
-----------------	--------------	-------	---------------------	---------------------------------	-------------------------	------------	-------------------------	------------	-----------	----------

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 01/31/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 01/31/2017 03:58:33 PM

Date Inspection Closed by Inspector: 01/31/2017 03:58:33 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

**Comments****Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/01/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 02/01/2017 02:25:21 PM

Date Inspection Closed by Inspector: 02/01/2017 02:25:21 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
--------------	-------------	------------------	----------------	-------------	-----------	----------------------	----------	---------	-------------------

TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	62.28	Defect Length : <b>0.1875</b>	113D8-113.D8 - Engine burn frac	FRA REMEDIAL ACTION CODE C	02/01/2017	Corr from Trk Mtce Plan	02/07/2017		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 02/04/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/04/2017 02:44:44 PM

**Date Inspection Closed by Inspector:** 02/04/2017 02:44:44 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

## TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 02/07/2017      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/07/2017 02:41:13 PM

**Date Inspection Closed by Inspector:** 02/07/2017 02:41:13 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
Track Traversed Information									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		50.00	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
Comments									

#### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8268 SIMN	71.20	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/07/2017	Corr from Trk Mtce Plan	02/07/2017		

#### Switch Defects

No switch defect records found

#### Joint Bar Inspections

No Joint Bar Inspections Found

#### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 02/07/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/07/2017 03:22:01 PM

**Date Inspection Closed by Inspector:** 02/07/2017 03:22:01 PM

#### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	50.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	50.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Comments</b>									

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked	ESTHERVILLE SUB	8253 SIMN	-	8.4	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	9.19	8253 INDU	02 -711	Hardy Elevator	Railbound Manganese
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.13	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	27.84	8253 INDU	02 -720	Ottosen Elevator	Spring-All Rail Extd length
Walked	ESTHERVILLE SUB	8253 SIMN	-	32.27	8253 INDU	02 -723	West Bend Processing	Railbound Manganese

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.27 32.26		133A4-133.A4 - Loose, worn, or	Repaired Before Traffic	02/07/2017	Corr from Trk Mtce Plan	02/07/2017		Tightened Jam Nut

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/10/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/10/2017 03:09:00 PM

**Date Inspection Closed by Inspector:** 02/10/2017 03:09:01 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02- 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

### Track Defects

No track defect records found

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8253 SIMN	32.27 32.26		121C2-121.C2 - Center cracked o	Repaired Before Traffic	02/10/2017	Corr from Trk Mtce Plan	02/10/2017		115/90 LH Comp Bars

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/11/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/11/2017 03:25:42 PM

**Date Inspection Closed by Inspector:** 02/11/2017 03:25:42 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

No track defect records found

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8268 SIMN	-	70.57	8268 YARD	02 -001	S. Switch Estherville Yard	RBM Standard Point
Walked	ESTHERVILLE SUB	8268 SIMN	-	71.21	8268 YARD	02 -001	Estherville Engine Track	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	70.56	8267 SIMN	-	Rake Junction Switch	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	71.17	8268 YARD	02 -503	N. Switch Estherville Yard	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	77.77	8268 INDU	02 -767	S. Switch Superior	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8268 SIMN	-	78.45	8268 INDU	02 -767	N Switch Superior	RBM Standard Point

### Switch Defects

--	--	--	--	--	--	--	--	--	--

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8268</u> SIMN	<u>71.17</u> 71.17		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/11/2017	Corr from Trk Mtce Plan	02/11/2017		Debris/ Rocks
ESTHERVILLE SUB	<u>8268</u> SIMN	<u>77.77</u> 77.75		133A9-133.A9 - Loose or missing	Repaired Before Traffic	02/11/2017	Corr from Trk Mtce Plan	02/11/2017		

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 02/13/2017      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/13/2017 02:24:19 PM

**Date Inspection Closed by Inspector:** 02/13/2017 02:24:19 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	---------------------	--	------	-------	----	---------	---------	-------------------------

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> SIMN	9.19		135D-135.D - Heel of switch in	Scheduled for Repair	02/13/2017	Corr from Trk Mtce Plan	03/03/2017		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 02/14/2017      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/14/2017 02:30:49 PM

Date Inspection Closed by Inspector: 02/14/2017 02:30:49 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	58.50		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/14/2017	Corr from Trk Mtce Plan	02/14/2017		

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/16/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 02/16/2017 03:35:25 PM

Date Inspection Closed by Inspector: 02/16/2017 03:35:25 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	32.20	32.23	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 809	47.18	47.22	No	REISWIG	DEURLOO	AG PROCESSORS
TWIN CITIES	ESTHERVILLE SUB	8253 YARD	02 724	33.54	33.57	No	REISWIG	DEURLOO	WEST BEND ELEVATOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		31.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	46.11	46.14	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 820	47.13	47.16	No	REISWIG	DEURLOO	VOYAGER ETHANOL, LLC
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		31.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
		8268							

TWIN CITIES	ESTHERVILLE SUB	SIMN	70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>								

### Track Defects

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8254</u> SIMN	59.65	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/16/2017	Corr from Trk Mtce Plan	02/16/2017		
ESTHERVILLE SUB	<u>8254</u> SIMN	69.43	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/16/2017	Corr from Trk Mtce Plan	02/16/2017		

### Switches Inspected

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/Track	ZTS		Segment/Track	ZTS		
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	31.03	<u>8253</u> SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.19	<u>8253</u> SIDE	02 -103	West Bend Siding	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	32.2	<u>8253</u> YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	33.57	<u>8253</u> YARD	02 -724	West Bend Elevator	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	46.11	<u>8253</u> INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	47.16	<u>8253</u> INDU	02 -820	Emmettsburg Ethanol	RBM Heavy Point
Walked/Operated	ESTHERVILLE SUB	<u>8253</u> SIMN	-	47.18	<u>8253</u> INDU	02 -809	Emmettsburg AGP	Spring-All Rail Extd length

### Switch Defects

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>32.20</u> 32.19		133A9-133.A9 - Loose or missing	Repaired Before Traffic	02/16/2017	Corr from Trk Mtce Plan	02/16/2017		
ESTHERVILLE SUB	<u>8253</u> SIMN	<u>32.20</u> 32.19		133A9-133.A9 - Loose or missing	Repaired Before Traffic	02/16/2017	Corr from Trk Mtce Plan	02/16/2017		

### Joint Bar Inspections

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	<u>8253</u> SIMN		31.00	48.49	REISWIG	DEURLOO	GOLDFIELD TO EMMETTSBURG
TWIN CITIES	ESTHERVILLE SUB	<u>8254</u> SIMN		48.49	70.56	REISWIG	DEURLOO	EMMETTSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	<u>8268</u> SIMN		70.56	78.46	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/18/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/18/2017 03:17:11 PM

**Date Inspection Closed by Inspector:** 02/18/2017 03:17:11 PM

### Tracks Inspected

--	--	--	--	--	--	--	--	--	--	--



Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 711	8.40	8.43	No	REISWIG	DEURLOO	GOLD EAGLE COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 730	48.71	48.95	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 732	58.50	58.53	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
TWIN CITIES	ESTHERVILLE SUB	8253 INDU	02 720	27.13	27.84	No	REISWIG	DEURLOO	FARMERS COOP
TWIN CITIES	ESTHERVILLE SUB	8254 CROS	77 269	48.59	48.64	No	REISWIG	DEURLOO	CROSS OVER (MAINLINE TO INDUSTRIAL SPUR)
TWIN CITIES	ESTHERVILLE SUB	8254 YARD	02 729	48.62	48.73	No	REISWIG	DEURLOO	AG PARTNERS
TWIN CITIES	ESTHERVILLE SUB	8254 INDU	02 733	59.40	59.43	No	REISWIG	DEURLOO	FARMERS COOP TRACKS
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	60.00	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8254 CNRT	02 117	48.49	48.58	No	REISWIG	DEURLOO	CONNECTION TO IMRL
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 CNRT 02 117	48.54		127A-127.A - Failure of fasten	Scheduled for Repair	02/18/2017	Corr from Trk Mtce Plan	03/08/2017		

**Switches Inspected**

Switch Inspected by	Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
		Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	ESTHERVILLE SUB	8254 YARD	02 - 729	48.64	8254 CROS	77 -269		RBM Standard Point
Walked	ESTHERVILLE SUB	8254 YARD	02 - 730	48.73	8254 YARD	02 -729		RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8253 SIMN	-	48.49	8254 CNRT	02 -117	Emmettsburg ICE Transfer	Railbound Manganese
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.59	8254 CROS	77 -269	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	48.95	8254 YARD	02 -730	Emmettsburg Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	58.5	8254 INDU	02 -732	Greattinger Elevator	RBM Standard Point
Walked/Operated	ESTHERVILLE SUB	8254 SIMN	-	59.43	8254 INDU	02 -733	Greattinger Elevator	RBM Standard Point

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	48.59 48.59		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	02/18/2017	Corr from Trk Mtce Plan	03/08/2017		5-Loose Frog Bolts
ESTHERVILLE SUB	8253 SIMN	48.49 48.49		127A-127.A - Failure of fasten	Scheduled for Repair	02/18/2017	Corr from Trk Mtce Plan	03/08/2017		
ESTHERVILLE SUB	8254 SIMN	58.50 58.50		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/18/2017	Corr from Trk Mtce Plan	02/18/2017		Ballast/ Debris

**Joint Bar Inspections**

Service Unit	Subdivision	Seg/ Zone/ Begin	End	Director	Manager	Track Description
--------------	-------------	------------------------	-----	----------	---------	-------------------

		Trk Type	Track	MP	MP			
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	31.00	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 02/21/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/21/2017 04:04:32 PM

**Date Inspection Closed by Inspector:** 02/21/2017 04:04:33 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	78.43	78.45	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8268 INDU	02 767	77.77	77.79	No	REISWIG	DEURLOO	SUPERIOR COOP
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 YARD	02 002	70.73	71.11	No	REISWIG	DEURLOO	CLASS.TR#2

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

**Comments**

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	69.80	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/21/2017	Corr from Trk Mtce Plan	02/21/2017		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 02/21/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/21/2017 04:10:20 PM

Date Inspection Closed by Inspector: 02/21/2017 04:10:20 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									
Estherville Sub MP 70.56 to MP 78.43 was omitted on Previous Report Dated Today									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

### Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 02/23/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 02/23/2017 03:51:11 PM

Date Inspection Closed by Inspector: 02/23/2017 03:51:12 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.25	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		32.25	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 02/26/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/26/2017 10:04:17 AM

**Date Inspection Closed by Inspector:** 02/26/2017 10:04:17 AM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
<b>Comments</b>									
Snow Covered Tracks									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**  
No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad**  
**FRA Track Inspection & Defect Report**

**Inspection Date:** 02/27/2017      **Inspected By:** Dustin Dickey  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/27/2017 02:47:29 PM

**Date Inspection Closed by Inspector:** 02/27/2017 02:47:29 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8253 SIDE	02 103	31.03	32.19	No	REISWIG	DEURLOO	WEST BEND SIDING
<b>Comments</b>									

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 02/28/2017      **Inspected By:** Gary Brockman  
**Inspection Type:** FRA Required      **Relief Inspector:** Data not entered  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 02/28/2017 02:37:12 PM

**Date Inspection Closed by Inspector:** 02/28/2017 02:37:12 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	59.43 59.43		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/28/2017	Corr from Trk Mtce Plan	02/28/2017		Snow /Ice
ESTHERVILLE SUB	8254 SIMN	58.50 58.50		133AG-133.A16 - Obstruction bet	Repaired Before Traffic	02/28/2017	Corr from Trk Mtce Plan	02/28/2017		Snow / Ice

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

**Inspection Date:** 03/01/2017      **Inspected By:** Kyle Olson  
**Inspection Type:** FRA Required      **Relief Inspector:** Brockman, Gary  
**Weather:** Data not entered      **How Conducted:** Hi-Rail Walk

Date Inspection Uploaded into the Central System: 03/01/2017 03:00:52 PM

Date Inspection Closed by Inspector: 03/01/2017 03:00:52 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	-----------	--	------	-------	----	---------	---------	-------------------------

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 03/02/2017	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Brockman, Gary
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

Date Inspection Uploaded into the Central System: 03/02/2017 02:34:00 PM

Date Inspection Closed by Inspector: 03/02/2017 02:34:00 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Track Traversed Information**

TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

**Comments**

**Track Defects**

No track defect records found

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/07/2017	<b>Inspected By:</b> Dustin Dickey
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Brockman, Gary
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/07/2017 02:48:29 PM

**Date Inspection Closed by Inspector:** 03/07/2017 02:48:29 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		33.00	48.49	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR

#### Comments

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

### Joint Bar Inspections

No Joint Bar Inspections Found

### TMP Joint Bar Re-Inspect

No TMP Joint Bar Re-Inspect Records Found

## Union Pacific Railroad FRA Track Inspection & Defect Report

<b>Inspection Date:</b> 03/08/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/08/2017 03:48:31 PM

**Date Inspection Closed by Inspector:** 03/08/2017 03:48:31 PM

### Tracks Inspected

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG

### Track Traversed Information

TWIN CITIES	ESTHERVILLE SUB	8253 SIMN		0.00	33.00	No	REISWIG	DEURLOO	GOLDFIELD TO EMMETSBURG
-------------	-----------------	--------------	--	------	-------	----	---------	---------	-------------------------

#### Comments

Also Accompanied by MTM David Deurloo Defects Are Shown On FRA Report # 23 Filed By Secora

### Track Defects

No track defect records found

### Switch Defects

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

**Union Pacific Railroad  
FRA Track Inspection & Defect Report**

<b>Inspection Date:</b> 03/09/2017	<b>Inspected By:</b> Gary Brockman
<b>Inspection Type:</b> FRA Required	<b>Relief Inspector:</b> Data not entered
<b>Weather:</b> Data not entered	<b>How Conducted:</b> Hi-Rail Walk

**Date Inspection Uploaded into the Central System:** 03/09/2017 03:47:40 PM

**Date Inspection Closed by Inspector:** 03/09/2017 03:47:40 PM

**Tracks Inspected**

Service Unit	Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
<b>Track Traversed Information</b>									
TWIN CITIES	ESTHERVILLE SUB	8254 SIMN		48.49	70.56	No	REISWIG	DEURLOO	EMMETSBURG TO ESTHERVILLE
TWIN CITIES	ESTHERVILLE SUB	8268 SIMN		70.56	78.46	No	REISWIG	DEURLOO	ESTHERVILLE TO SUPERIOR
<b>Comments</b>									

**Track Defects**

Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
ESTHERVILLE SUB	8254 SIMN	49.50	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	03/09/2017	Corr from Trk Mtce Plan	03/09/2017		
ESTHERVILLE SUB	8254 SIMN	69.76	Number of Bolts : 3	121E-121.E - Less than 2 bolts	Repaired Before Traffic	03/09/2017	Corr from Trk Mtce Plan	03/09/2017		

**Switch Defects**

No switch defect records found

**Joint Bar Inspections**

No Joint Bar Inspections Found

**TMP Joint Bar Re-Inspect**

No TMP Joint Bar Re-Inspect Records Found

>