



Photo 5 - Broken tie down across the lower forward section of the oversize load