



**VEHICLE FACTORS GROUP CHAIRMAN'S
FACTUAL REPORT**

**Vehicle Attachment 12 – Specifications and Recall Information
for the 2014 Cadillac CTS**

**MULTIPLE VEHICLE ACCIDENT
Chattanooga, TN**

HWY15MH009

(7 pages)

VINquery.com Report - 7/29/2015

VIN #	1G6AU5S88E0 [REDACTED]
VINquery.com Vehicle ID	47088
Model Year	2014
Make	Cadillac
Model	CTS
Trim	3.6L Twin Turbo Vsport Performance RWD
Manufactured in	UNITED STATES
Production Seq. Number	183232

Specifications

Body Style	SEDAN 4-DR
Engine Type	3.6L V6 DOHC 24V TWIN-TURBO
Transmission	8-Speed Automatic
Driveline	RWD
Tank(gallon)	19.00
Fuel Economy(City, miles/gallon)	No data
Fuel Economy(Highway, miles/gallon)	No data
Anti-Brake System	4-Wheel ABS
Steering Type	R&P
Seating(standard)	5
Seating(optional)	No data
Length(in.)	195.50
Width(in.)	72.20
Height(in.)	57.20

Disclaimer

ALTHOUGH VINQUERY.COM CHECKS REGULARLY WITH ITS DATA SOURCES TO CONFIRM THE ACCURACY AND COMPLETENESS OF THE DATA, IT MAKES NO GUARANTY OR WARRANTY, EITHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OR MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE, WITH RESPECT TO THE DATA PRESENTED IN THIS REPORT. USER ASSUMES ALL RISKS IN USING ANY DATA IN THIS REPORT FOR HIS OR HER OWN APPLICATIONS. ALL DATA IN THIS REPORT ARE SUBJECT TO CHANGE WITHOUT NOTICE.

© 2006 - 2015 VINquery.com - Auto Databank, Inc. All rights reserved.

2014 CADILLAC CTS 3.6L RWD SEDAN

A	Longitudinal distance between the center of the front bumper and the center of the base of the windshield	57.1 in
B	Passenger Car Longitudinal distance between the center of the rear bumper and the center of the base of the backlight Station Wagon and Vans Longitudinal distance between the backlight top moulding and the front door latch pillar Pick-ups Longitudinal distance between the rearmost projection and the front door latch pillar	24.0 in
C	The maximum vertical height of the side glass	13.4 in
D	Vertical distance between the base of the side glass and the lower edge of the rocker panel	33.5 in
E	Distance between side rails or maximum width of top	42.6 in
F	Front overhang	34.3 in
G	Rear overhang	46.9 in
OL	Overall length	195.8 in
OW	Overall width	72.1 in
OH	Overall height	57.1 in
WB	Wheelbase	114.7 in
TWF	Front track width	61.5 in
TWR	Rear track width	61.9 in
CW	Curb weight	3817 lb
WD	Weight distribution (Front/Rear)	52/48

Measurements obtained in year: 14

Search Results



2014 CADILLAC CTS

Recalls

5 Result(s)

Investigations

0 Result(s)

Complaints

18 Result(s)

Service Bulletins

23 Result(s)

RECALLS: Displaying 1 - 5 out of 5

— RECALL Subject : Contamination of the Chassis Electronic Module

Report Receipt Date: OCT 01, 2014
 NHTSA Campaign Number: 14V614000
 Component(s): ELECTRICAL SYSTEM

All Products Associated with this Recall ▼

Details ▲

22 Associated Documents ▼

Manufacturer: General Motors LLC

SUMMARY:

General Motors LLC (GM) is recalling certain model year 2013-2014 Cadillac CTS, Escalade, Escalade ESV, Chevrolet Suburban, Tahoe, GMC Yukon, and Yukon XL, and 2014 Buick Enclave, Chevrolet Express, Impala, Silverado HD, Traverse, GMC Acadia, Savana, and Sierra HD vehicles. In the affected vehicles, the chassis electronic module may be internally contaminated, resulting in an electrical short.

CONSEQUENCE:

If the module experiences an electrical short, the vehicle could stall, increasing the risk of a crash.

REMEDY:

GM will notify owners, and dealers will replace the chassis electronic module, free of charge. The recall began on December 26, 2014. Owners may contact GM customer service at 1-800-521-7300 (Buick), 1-800-458-006 (Cadillac), 1-800-222-1020 (Chevrolet), and 1-800-462-8782 (GMC). GM's number for this recall is 14515.

NOTES:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

— RECALL Subject : Front Seats may not Remain Anchored in Vehicle

Report Receipt Date: JUL 23, 2014
 NHTSA Campaign Number: 14V446000
 Component(s): SEATS

All Products Associated with this Recall ▼

Details ▲

15 Associated Documents ▼

Manufacturer: General Motors LLC

SUMMARY:

General Motors LLC (GM) is recalling certain model year 2013-2014 Buick Encore and Cadillac ATS; 2014 Cadillac CTS, ELR, Chevrolet Caprice and SS vehicles; and 2014-2015 Chevrolet Silverado and GMC Sierra Trucks. Due to an incomplete weld on the seat hook bracket assembly, the front seats in the affected vehicles may not stay secured in place during a high load condition such as a crash.

CONSEQUENCE:

A seat that does not stay secured increases the risk of occupant injury in a vehicle crash.

REMEDY:

GM will notify owners, and dealers will inspect the seat hook bracket assembly weld and replace the lower seat track, as necessary, free of charge. The recall began on August 15, 2014. Owners may contact GM customer service at 1-800-521-7300 (Buick), 1-800-458-8006 (Cadillac), 1-800-222-1020 (Chevrolet), and 1-800-462-8782 (GMC). GM's number for this recall is 14340.

NOTES:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

— RECALL Subject : Ignition Switch may Turn Off

Report Receipt Date: JUL 02, 2014
 NHTSA Campaign Number: 14V394000
 Component(s): ELECTRICAL SYSTEM

All Products Associated with this Recall ▼

Details ▲

36 Associated Documents ▼

Manufacturer: General Motors LLC

SUMMARY:

This defect can affect the safe operation of the airbag system. Until this recall is performed, customers should remove all items from their key rings, leaving only the ignition key. The key fob (if applicable), should also be removed from the key ring. General Motors LLC (GM) notified the agency on July 2, 2014 that they are recalling 554,328 model year 2003-2014 Cadillac CTS vehicles manufactured August 16, 2001, to April 28, 2014, and 2004-2006 Cadillac SRX vehicles manufactured March 20, 2003, to August 11, 2006. In these models, the weight on the key ring and/or road conditions or some other jarring event may cause the ignition switch to move out of the run position, turning off the engine.

CONSEQUENCE:

If the key is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury.

REMEDY:

GM will notify owners, and dealers will install two key rings and an insert in the key slot or a cover over the key head on all ignition keys, free of charge. The recall began on September 15, 2014. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is 14172.

NOTES:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

— RECALL Subject : Transmission Shift Cable Detachment/Rollaway Risk

Report Receipt Date: JUN 19, 2014
 NHTSA Campaign Number: 14V338000
 Component(s): POWER TRAIN

All Products Associated with this Recall ▼

Details ▲

14 Associated Documents ▼

Manufacturer: General Motors LLC

SUMMARY:

General Motors LLC (GM) is recalling certain model year 2013-2014 Cadillac ATS vehicles manufactured April 23, 2012, to March 20, 2014, and 2014 Cadillac CTS vehicles manufactured June 10, 2013, to March 20, 2014. In the affected vehicles, the transmission shift cable may detach from either the bracket on the transmission shifter or the bracket on the transmission.

CONSEQUENCE:

If the transmission shift cable detaches while the vehicle is being driven, the transmission gear selection may not match the indicated gear and the vehicle may move in an unintended or unexpected direction, increasing the risk of a crash. Furthermore, when the driver goes to stop and park the vehicle, despite selecting the 'PARK' position, the transmission may not be in 'PARK.' If the vehicle is not in the 'PARK' position there is a risk the vehicle will roll away as the driver and other occupants exit the vehicle or anytime thereafter. A vehicle rollaway increases the risk of injury to exiting occupants and bystanders.

REMEDY:

GM will notify owners, and dealers will inspect the vehicles to make sure the cable is properly seated at the transmission and shifter brackets, free of charge. The recall is expected to begin in early August 2014. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is 14179.

NOTES:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

— RECALL Subject : Wiper System may become Inoperable

Report Receipt Date: MAY 15, 2014
NHTSA Campaign Number: 14V253000
Component(s): VISIBILITY

All Products Associated with this Recall ▼

Details ▲

10 Associated Documents ▼

Manufacturer: General Motors LLC

SUMMARY:

General Motors LLC (GM) is recalling certain model year 2014 Cadillac CTS vehicles manufactured June 10, 2013, through February 26, 2014. If the vehicle is turned off with wiper functionality left on and the wipers then become restricted, such as when covered in ice or snow, and the vehicle's battery goes dead and needs to be jump started, upon being jump started, the wipers will be inoperative.

CONSEQUENCE:

An inoperative windshield wiper system may decrease the driver's visibility, increasing the risk of a crash.

REMEDY:

GM will notify owners, and dealers will replace the front wiper module, free of charge. The recall began on July 14, 2104. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is 14157.

NOTES:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA 1.888.327.4236 TTY 1.800.424.9153

6.0.12.3

Email

Recalls Results by VIN - Vehicle Identification Number

Print



VIN: 1G6AU5S88E0183232

Year: 2014 Make: Cadillac Model: CTS A

Number of Open Recalls: 0

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues section](#) and follow the instructions there.

Recall information for this manufacturer is only available going back to August 20, 1999. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

Enter another VIN here: 1G6AU5S88E0



Type the text

[Privacy & Terms](#)

Submit