

Vehicle Attachment 8 2000 Setra Recall and Warranty Information

Doswell, VA HWY-11-MH-010

(3 Pages)



Recalls - Search Results

2 Record(s) Displayed.

Report Date: August 24, 2011 at 02:20 PM

Search Type: VEHICLE Make: SETRA

Model or Model No.: \$217 Model Year: 2000

Make: SETRA Model: S217

Model Year: 2000

Manufacturer: SETRA OF NORTH AMERICA Mfr's Report Date: MAY 09, 2008 NHTSA CAMPAIGN ID Number: 08V219000 NHTSA Action Number: N/A

Component: POWER TRAIN: AXLE HUBS

Summary: SETRA IS RECALLING 265 MY 1994-2002 S217 HDH MOTOR COACHES, DUE TO THE RESULT FROM HIGH LOAD ON THE VEHICLES, THE WHEEL HUB AT THE FRONT AXLE COULD BECOME DAMAGED, FATIGUE AND FRACTURE.

THE FLANGE MAY SEPARATE FROM THE WHEEL AND THEN COMPLETELY BECOME LOOSE FROM THE VEHICLE INCREASING THE RISK OF A CRASH.

DEALERS WILL CHANGE THE WHEEL HUB WITH A REINFORCED WHEEL HUB FREE OF CHARGE. THE RECALL BEGAN ON DECEMEBER 23, 2008. OWNERS MAY CONTACT SETRA AT 1-800-882-8054.

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

Make: SETRA Model: S217

Model Year: 2000

Manufacturer: SETRA OF NORTH AMERICA Mfr's Report Date: JAN 28, 2009 NHTSA CAMPAIGN ID Number: 09V044000 NHTSA Action Number: N/A

Component: EQUIPMENT:OTHER:LABELS

Summary:

SETRA IS RECALLING 490 MY 1984-2001 S215, MY 1994-2002 S217 AND MY 2003-2009 S417 MOTOR COACHES EQUIPPED WITH EMERGENCY EXITS. THESE MOTOR COACHES FAIL TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 217, "BUS EMERGENCY EXITS AND WINDOW RETENTION AND RELEASE." WHEN A RELEASE MECHANISM IS NOT LOCATED WITHIN AN OCCUPANT SPACE OF AN ADJACENT SEAT, A LABEL MEETING THE REQUIREMENTS OF \$5.5.2 THAT INDICATES THE LOCATION OF THE NEAREST RELEASE MECHANISM SHALL BE PLACED WITHIN THE OCCUPANT SPACE. EXAMPLE: "EMERGENCY EXIT INSTRUCTIONS LOCATED NEXT TO SEAT AHEAD" THESE LABELS ARE NOT INSTALLED IN THE MOTOR COACHES MENTIONED IN THE EXAMPLE ABOVE.

Consequence:

IN THE EVENT OF A CRASH, WITHOUT THE CORRECT INSTRUCTIONS A PASSENGER MAY NOT KNOW HOW TO UNLATCH AND OPEN THE EMERGENCY EXIT INCREASING THE RISK OF INJURY.

DEÁLERS WILL SEND LABELS WITH A SERVICE INSTRUCTIONS EXPLAINING THE LOCATION OF THE LABELS FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING MARCH 2009. OWNERS MAY CONTACT SETRA AT 1-800-882-8054.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .





FIN:

WKK 626028 13

Current advice for the vehicle:

none

Outstanding KDM:

none

ESKULAB decisions:

none

Damage history:

Тур	Rep. Date	х	#	Damage code	Damage code description	Claim No.	L. KZ	Area	ш	М	E	Credit note no.	Credit note date
×	06.05.201 0	,	12	067920607	\$TI67.10U06585A 28 0903O67M01 S417 USA Update emergency exit 09V-044 09-033	329657		70559	592083	mi s	1	00000057 1	14.05.2010
*	06.05.201 0		11	033920697	\$TI35.10U06387A 28 RADNABEN Wheel hub exchange S217HDH, S317 HDH, S217 HDH- USA	329657A		70559	592083	ml s	1	00000057 1	14.05.2010
×	12.06.200 2		10			000204		70559	1500	ml s	0	00000000	23.11.2002
*	09.06.200 2		9			70007		70559	1000	ml s	0	00000000	24.08.2002
×	08.06.200 2	AA	8			70004		70559	172009	ml s	0	00000000	24.08.2002
爽	08.06.200 2	AA	7			70004		70559	172009	ml s	0	00000000	24.08.2002
*	08.06.200 2		6			70004		70559	172009	ml s	0	00000000	24.08.2002
*	08.06.200 2	ΑB	5			70004		70559	172009	mi s	0	00000000	24.08.2002
×	08.06.200 2		4			70004		70559	172009	mi s	0	00000000	24.08.2002
K	26.01.200 1	AC.	3			203610		70559	38732	km	0	00000000	
*	27.10.200 0	AB	2			199110		70559	22824	km	0	00000000	25.03.2001
*	27.10.200 0		1			199110		70559	22824	km	0	00000000	25.03.2001

101.06.20 ⁻
