



## **NTSB Vehicle Photos**

**Oakland, Iowa**

**HWY18MH003**

(2 pages)



Vehicle Photo #1 – Overall view of the damage to the right side of the 2004 IC School Bus during inspection at Arrow Towing in Council Bluffs, Iowa.



Vehicle Photo #2 – View of the damage to the right rear corner of the school bus.