



Photo 1 – Airplane at Accident Site (Photo Provided by Airplane Owner/Operator)



Photo 2 – Left Wing Rear Spar Damage (Photo Provided by Airplane Owner/Operator)