

ERA24LA064

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft Overview (Courtesy of FAA)



Photograph 2 - Damage to left wing (Courtesy of FAA)



Photograph 3 - Damage to right wing (Courtesy of FAA)



Photograph 4 - Runway/Taxiway skid marks and propeller strikes (Courtesy of FAA)