

ERA24LA138

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photograph of airplane on runway (Courtesy of FAA)



Photograph 2 - Damage to airplane structure (Courtesy of FAA)



Photograph 3 - Damage to airplane structure (Courtesy of FAA)



Photograph 4 - Bent right main landing gear push rod (Courtesy of A&P mechanic)



Photograph 5 - Bent right main landing gear push rod (Courtesy of A&P Mechanic)



Photograph 6 - Bent left main landing gear push rod (Courtesy of A&P Mechanic)