



Highway Factors Photographs 1 through 9

Williamsburg, VA

HWY23MH004

(8 pages)



Highway Factors Photo 1 – View of strong post blocked-out W-beam guardrail that contained the Freightliner combination vehicle within the median standing in the leftmost travel lane in the westbound direction looking to the northwest (Source: Virginia State Police)



Highway Factors Photo 2 – View of strong post blocked-out W-beam guardrail that contained the Freightliner combination vehicle within the median standing in the paved shoulder adjacent to the leftmost travel lane in the westbound direction looking to the northwest (Source: Virginia State Police)



Highway Factors Photo 3 – View of strong post blocked-out W-beam guardrail that contained the Freightliner combination vehicle within the median standing in the leftmost travel lane in the westbound direction looking to the southeast (Source: Virginia State Police)



Highway Factors Photo 4 – View of strong post blocked-out W-beam guardrail that contained the Freightliner combination vehicle within the median standing in the paved shoulder adjacent to the leftmost travel lane in the westbound direction looking to the southeast (Source: Virginia State Police)



Highway Factors Photo 5 – View of tire marks left in the median by the Freightliner combination vehicle standing in the paved shoulder adjacent to the leftmost travel lane in the westbound direction looking to the northwest



Highway Factors Photo 6 – View of tire marks left in the median by the Freightliner combination vehicle standing in the paved shoulder adjacent to the leftmost travel lane in the eastbound direction looking to the southeast



Highway Factors Photo 7 – View of median separating the eastbound travel lanes from the westbound travel lanes looking to the southeast



Highway Factors Photo 8 – View of deformed W 6 x 9 steel I-beam posts standing in the paved shoulder adjacent to the leftmost travel lane in the eastbound direction looking to the southeast



Highway Factors Photo 9 – Close up view of deformed W 6 x 9 steel I-beam posts standing in the paved shoulder adjacent to the leftmost travel lane in the eastbound direction looking to the southeast