



**Vehicle Attachment – Vehicle Factors Photographs**

**Clarendon Hills, IL**

**HWY22MH009**

(4 pages)



**Photograph 1:** An image of the bottom of the engine compartment and displaced transmission.



**Photograph 2:** An image of the damaged oil pan and rearward displacement of the steering axle.



**Photograph 3:** An image of the left side of the cab after the truck up righted.



**Photograph 4:** An image of the right side of the cab after the truck was up righted.



**Photograph 5:** An image (looking from the right side toward the left side) of the cab interior.



**Photograph 6:** An image of the displaced steering gear at the crash scene.