

# Engineering Job Briefing Form

Team # SF11  
 Date: 11/30/18 Time: 0700  
 CPR: John  
 Hospital: Hampton Regional  
 Injury Free Days: Team \_\_\_\_\_ Div. \_\_\_\_\_

## Sequence of Events

Location: Estill  
 Task Description: assist welder repairing frog

## Hazard Recognition & Control

Hazards	Controls
2,3 S,T,F / noses, Rail, tools, loose ballast	
2,3 Pinch points / bin doors, tailgate on truck	
2,3 PPE / leggings, shield - if grinding,	
2,3 Welding hood - if welding	
2,3 Reflective vest/shirt, hard hat, glasses	
2,3 gloves	

## Equipment

Proper tools:  Yes  No Inspect tools:  Yes  No  
 Boom flag:  Yes  No Special PPE: \_\_\_\_\_

## Protection - Type of On-Track Protection

707 704 SOTS  
 Authority# \_\_\_\_\_ Disp \_\_\_\_\_ OK \_\_\_\_\_  
 Time: From \_\_\_\_\_ To \_\_\_\_\_ EIC: \_\_\_\_\_  
 Limits: \_\_\_\_\_ Track # \_\_\_\_\_  
 Authority# \_\_\_\_\_ Disp \_\_\_\_\_ OK \_\_\_\_\_  
 Time: From \_\_\_\_\_ To \_\_\_\_\_ EIC: \_\_\_\_\_  
 Limits: \_\_\_\_\_ Track # \_\_\_\_\_  
 Authority# \_\_\_\_\_ Disp \_\_\_\_\_ OK \_\_\_\_\_  
 Time: From \_\_\_\_\_ To \_\_\_\_\_ EIC: \_\_\_\_\_  
 Limits: \_\_\_\_\_ Track # \_\_\_\_\_  
 704-A: Switches Yes No Derails Yes No  
 Watchman/Lockout: Speed \_\_\_\_\_ Sight Distance \_\_\_\_\_

## Understanding

Do all team members understand briefing? Yes No