

Photo 1- View of the wreckage under the canopy of trees in a wooded area.



Photo 2 - View of the wreckage under the canopy of trees in a wooded area.



Photo 3 - View of a separated tree trunk under the canopy of trees in a wooded area.



Photo 4 - View of a separated tree trunk and separated airplane parts lodged in the tree trunk under the canopy of trees in a wooded area.



Photo 5 - View of a separated wing.



Photo 6 - View of a separated wing section.



Photo 7 - View of a separated wing section.



Photo 8 - View of a separated control tube within a separated wing section.



Photo 9 - Close-up view of a separated tree trunk and separated airplane parts lodged in the tree trunk under the canopy of trees in a wooded area.



Photo 10 - Close-up view of a separated spar recovered from a separated tree trunk.



Photo 11 - View of removed sparkplugs.



Photo 12 - View of the disassembled engine driven fuel pump.



Photo 13 - View of the crankshaft from the disassembled engine.



Photo 14 - View of the camshaft from the disassembled engine.



Photo 15 - View of a removed cylinder.



Photo 16 - View of the underside of the fuselage and empennage.



Photo 17 - View of the engine embedded in terrain.



Photo 18 - Close-up view of the engine embedded in terrain.




Photo 19 - Close-up view of the ignition switch.



Photo  ${\bf 20}$  - View of the vertical stabilizer indicating the airplane's N-number.