

Photo 1 – View of the open as received package containing the FADEC Master Power Control unit (MPC) and speed sensor.



Photo 2 - View of the open as received package containing the FADEC MPC unit and speed sensor.




Photo 3 - View of the wiring connector to the FADEC MPC unit.




Photo 4 - View of the electromagnetic interference (EMI) gasket and sealant strip associated with the connector.



Photo 5 - View of an accident FADEC MPC connected to a testing system.



Photo 6 - View of the data associated with testing the accident FADEC MPC.




Photo 7 - View of sparkplugs attached to the accident FADEC MPC.




Photo 8 - View of the speed sensor.




Photo 9 - View of the speed sensor connected to a testing system.




Photo ${\bf 10}$ - View of the FADEC MPC and speed sensor packaged for return.