

**On Scene Images
WPR19FA124**



Figure 1 - Airplane at Impact Location



Figure 2 - Impact Location

**On Scene Images
WPR19FA124**



Figure 3 - After Removal From Pond



Figure 4 - Impact Location

**On Scene Images
WPR19FA124**



Figure 5 - After Removal From Pond



Figure 6 - After Removal From Pond

**On Scene Images
WPR19FA124**



Figure 7 - Left Wing



Figure 8 - Left Wing and Retracted Flap

**On Scene Images
WPR19FA124**



Figure 9 - Deflected Pitch Trim Tab

**On Scene Images
WPR19FA124**



Figure 10 - Instrument Panel

On Scene Images
WPR19FA124



Figure 11 - Instrument Panel

On Scene Images
WPR19FA124



Figure 12 - Left Instrument Panel

**On Scene Images
WPR19FA124**



Figure 13 - Right Instrument Panel

**On Scene Images
WPR19FA124**



Figure 14 - Canopy Frame and Aft Bulkhead

**On Scene Images
WPR19FA124**



Figure 15 - Pilot's Shoulder Harness