

Communication Summary

January 5, 2021

Communication From: Don Maxwell, mechanic



Mr Maxwell was advised the airplane logbooks were not located. He and the prior owner were asked if the SBs and AD regarding the trim system were accomplished.

Mr. Maxwell, in part, stated that those items were not shown it on the work order, but it would have shown on the AD list. It is a normal part of our annual check list so I am sure it was complied with previously or it would have been listed on the work order as an action item.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator